

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23002953/RQY3Q2**Date:** 26/06/2023**REFERENCE**

Insured/Claimant:	CHIA WEE LIANG	Policy No:	SP2002756873-01	
Date of Loss:	17/03/2023	Nature of Claim:	OD	Claim No: 202332006341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL7106L		Engine No:	CGW013427
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)		Chassis No:	WAUZZZ4G7BN026252
Reg. Date:	31/08/2011 (Man. Year: 2011)		Odometer:	138723 km
Colour:	Black			
Engine Capacity:	2995 cc			
Market Value/New Car Price:	S\$103,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R19	Rear Tyre Size:	245/40Z R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	820.00	770.00	50.00	6.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,160.00	920.00	44.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,900.00	1,930.00	970.00	33.45
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	2,400.00	1,430.00	970.00	40.42
+ GST 8.00/8.00% (\$\$)	192.00	114.40	77.60	40.42
Nett Amount (\$\$)	2,592.00	1,544.40	1,047.60	40.42

INSPECTION

Date of Assignment:	21/03/2023	
Date Inspected:	22/03/2023	Inspected At: 48 TOH GUAN ROAD EAST, #05-136, ENTERPRISE HUB, SINGAPORE 608586 Repairer: AVANTAGE VAG (TOH GUAN) (HQ)
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2023)
Parts:	143	AUDI A6 1.8 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL7106L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP OUTER RH (WCP)	Cracked	700.00 F	*700.00 F
2	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					750.00	700.00
+ Margin on L,N Items 10.00/10.00% (S\$)					70.00	70.00
Total Parts (S\$)					820.00	770.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SURFACE PREPARATION SPRAY PAINT AND DETAILING OF REAR BUMPER ,REAR FENDER RH AND OTHER AFFECTED PANELS	New	1,000.00	600.00
2	REMOVE AND REFITTING OF REAR BUMPER ,REAR TAILLAMP RH ,REAR FENDER RH PANEL BEATING AND OTHER AFFECTED AREAS	New	1,000.00	500.00
3	TO PERFORM DIAGNOSTICS CHECK WIRE CONNECTOR AND CLEARING OF FAULTS AFTER REPAIR	New	80.00	60.00
Gross Labour Cost (\$\$)			2,080.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >