

ASS. REC. BY:

REF:

ALS / 23 002954 / KP

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMF 1869T

Yr Regn:

10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M. D. Green

A/C:

Insured / Std / NI / NA

Sp. Reading

366722

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTD 8S 3EU 80 J034700

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / RIM or

Tyre Size:

F: Pirelli 205/60R18

R: Aviro

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

3 mm

L/Bal.

7 mm

L/Bal.

3 mm

D.O.A.

18/3/23

D.O.I.

23/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

C/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/3 11pm @ 3100h Curb

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$)

Date: 21/03/2023

Vehicle No: SMF1869T

Model: TOYOTA PRIUS PLUS

Chassis: JTDZS3EU80J034700-2018

Reg.Year: 2018

*Not with out  
1/1 up 83100h  
Resony After Rain  
7 days*

Third Party Insurer: ALLIANZ

Third Party Veh No: SJQ5500H

Date of Accident: 18/03/2023

Estimator: TING AN

Surveyor:

## ESTIMATE

| NO.         | DESCRIPTION                  | QTY | UNIT S\$ | AMOUNT S\$  |
|-------------|------------------------------|-----|----------|-------------|
| 1           | FRONT HEADLAMP RH            | 1   | 52       | \$2,526.00  |
| 2           | FRONT BUMPER                 | 1   | Mycom    | \$556.00    |
| 3           | FRONT BUMPER SIDE BRACKET RH | 1   | Di'l     | \$92.00     |
| 4           | FRONT FENDER RH 321          | 1   | Ry       | \$921.00    |
| 5           | FRONT FENDER "HYBRID" EMBLEM | 1   | mu       | \$60.00     |
| 6           | FRONT FENDER INNER SHIELD RH | 1   | Di'l     | \$172.00    |
| 7           | FRONT RIM COVER 148          | 1   | Net      | \$254.00    |
| 8           | FRONT DOOR RH                | 1   | R        | \$1,408.00  |
| 9           | FRONT DOOR UPPER HINGE RH    | 1   | R        | \$90.00     |
| 10          | FRONT DOOR LOWER HINGE RH    | 1   | R        | \$90.00     |
| 11          | FRONT DOOR CHECKER RH        | 1   | lu       | \$199.00    |
| 12          | REAR DOOR RH                 | 1   | R        | \$1,401.00  |
| 13          | REAR FENDER RH               | 1   | R        | \$1,055.00  |
| 14          | REAR FENDER MUDFLAP RH       | 1   | pu       | \$98.00     |
| 15          | REAR RIM COVER RH 148        | 1   | my       | \$254.00    |
| 16          | REAR BUMPER                  | 1   | Mycom    | \$549.00    |
| 17          | REAR BUMPER SIDE BRACKET RH  | 1   | Di'l     | \$144.00    |
| 18          | ROCKER PANEL RH              | 1   |          | REPAIR      |
| SUB TOTAL   |                              |     |          | \$9,869.00  |
| LESS 25%    |                              |     |          | -\$2,467.25 |
| PARTS TOTAL |                              |     |          | \$7,401.75  |

| NO.       | SPECIAL NETT                         | QTY | UNIT S\$ | AMOUNT S\$ |
|-----------|--------------------------------------|-----|----------|------------|
| 1         | FRONT BUMPER CLIPS                   | 1   | mu       | \$50.00    |
| 2         | FRONT FENDER INNER SHIELD CLIPS RH   | 1   | mu       | \$40.00    |
| 3         | FRONT DOOR INNER TRIM BOARD CLIPS RH | 1   | mu       | \$40.00    |
| 4         | REAR DOOR INNER TRIM BOARD CLIPS RH  | 1   | mu       | \$40.00    |
| 5         | REAR FENDER QUARTER GLASS SEALANT RH | 1   | mu       | \$80.00    |
| 6         | REAR BUMPER CLIPS                    | 1   | mu       | \$50.00    |
| S/N TOTAL |                                      |     |          | \$300.00   |

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 21/03/2023  
Vehicle No: SMF1869T  
Model: TOYOTA PRIUS PLUS  
Chassis: JTDZS3EU80J034700-2018  
Reg.Year: 2018

Third Party Insurer: ALLIANZ  
Third Party Veh No: SJQ5500H  
Date of Accident: 18/03/2023  
Estimator: TING AN  
Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

700  
\$1,500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER, ROCKER PANEL RH & ETC.

1200  
\$1,500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

nn \$120.00 X

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

nn \$120.00 X

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS, REAR FENDER QUARTER GLASS SEALANT & ETC.

nn \$150.00 X

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

nn \$250.00 X

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 300

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 300

LABOUR TOTAL \$3,880.00

TING AN

TOTAL \$11,581.75

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 556800  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-09 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

