

Date: 21/03/2023

Vehicle No: SMF1869T

Model: TOYOTA PRIUS PLUS

Chassis: JTDZS3EU80J034700-2018

Reg.Year: 2018

Third Party Insurer: ALLIANZ

Third Party Veh No: SJQ5500H

✓Date of Accident: 18/03/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1	PL	\$2,526.00
2	FRONT BUMPER	1		\$556.00
3	FRONT BUMPER SIDE BRACKET RH	1		\$92.00
4	FRONT FENDER RH	1		RF \$921.00
5	FRONT FENDER "HYBRID" EMBLEM	1		RF \$60.00
6	FRONT FENDER INNER SHIELD RH	1		D-7 \$172.00
7	FRONT RIM COVER	1		RF \$254.00
8	FRONT DOOR RH	1		RF \$1,408.00
9	FRONT DOOR UPPER HINGE RH	1		RF \$90.00
10	FRONT DOOR LOWER HINGE RH	1		RF \$90.00
11	FRONT DOOR CHECKER RH	1		PL \$199.00
12	REAR DOOR RH	1		RF \$1,401.00
13	REAR FENDER RH	1		RF \$1,055.00
14	REAR FENDER MUDFLAP RH	1		PL \$98.00
15	REAR RIM COVER RH	1		RF \$254.00
16	REAR BUMPER	1	MF & M	\$549.00
17	REAR BUMPER SIDE BRACKET RH	1		D-11 \$144.00
18	ROCKER PANEL RH	1		REPAIR
			SUB TOTAL	\$9,869.00
			LESS 25%	-\$2,467.25
			PARTS TOTAL	\$7,401.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		\$50.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>nn</i> \$40.00
3	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$40.00
4	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$40.00
5	REAR FENDER QUARTER GLASS SEALANT RH	1		<i>nn</i> \$80.00
6	REAR BUMPER CLIPS	1		<i>nn</i> \$50.00
			S/N TOTAL	\$300.00

Date: 21/03/2023
Vehicle No: SMF1869T
Model: TOYOTA PRIUS PLUS
Chassis: JTDZS3EU80J034700-2018
Reg.Year: 2018

Third Party Insurer: ALLIANZ
Third Party Veh No: SJQ5500H
Date of Accident: 18/03/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

700
\$1,500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER, ROCKER PANEL RH & ETC.

1200
\$1,500.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

nn \$120.00 *X*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

nn \$120.00 *X*

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS, REAR FENDER QUARTER GLASS SEALANT & ETC.

nn \$150.00 *X*

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

nn \$250.00 *X*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 *300*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *300*

LABOUR TOTAL \$3,880.00

TING AN

TOTAL

\$11,581.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Branch (Motor Insurance Claims)

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Blk 10 Ang Mo Kio Ind. Park 2A #01-06 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

