

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23002955/SVY3Q2**Date:** 30/03/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS008156
Claimant Vehicle No :	SHC1079G	Insured Vehicle No :	SJP7532H
Date of Loss:	19/03/2023	Nature of Claim:	TP
		Claim No:	M2301823

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1079G	Engine No:	G4LEGU330035
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU106514
Reg. Date:	10/08/2018 (Man. Year: 2018)	Odometer:	616476 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,491.44	557.12	1,934.32	77.64
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,080.00	900.00	1,180.00	56.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,582.44	1,468.12	3,114.32	67.96
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	4,582.44	1,150.00	3,432.44	74.90
+ GST 8.00/8.00% (S\$)	366.60	92.00	274.60	74.90
Nett Amount (S\$)	4,949.04	1,242.00	3,707.04	74.90

INSPECTION

Date of Assignment:	22/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/03/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1079G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	2,147.90 FL	*- FL
2	1		*REAR WHEEL CAP RH	Scratched	346.40 FL	*346.40 FL
3	1		*REAR DOOR APPS RH	Necessary	80.00 F	*80.00 F
4	1		*REAR DOOR ADVERTISEMENT STICKER RH	Necessary	100.00 F	*100.00 F
5	1		*REAR FENDER ADVERTISEMENT STICKER RH	Necessary	100.00 F	*100.00 F
6	1		*REAR WESTLAKE TYRE RH	Not Necessary	216.00 F	*- F
Sub Total (\$\$)						2,990.30 626.40
- List Item Discount on L Items 20.00/20.00% (\$\$)						498.86 69.28
Total Parts (\$\$)						2,491.44 557.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING - REAR FENDER ARCH RH ETC	New	800.00	500.00
2	SPRAY PAINTING - REAR BUMPER ETC	New	900.00	250.00
3	TUFF KOTE	New	80.00	0.00
4	TRANSFER OF DOOR	New	120.00	60.00
5	WHEEL ALIGNMENT	New	120.00	30.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
6	TOWING FEE (tow chit attached)	New	60.00	60.00
Gross Labour Cost (\$\$)			2,080.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >