

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 22.02.2023INSURANCE: INCOME (LKS)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC3438R

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper <i>scr R</i>	1		\$ 481.10 <i>R</i>
	Front Bumper Clips <i>XIV</i>	10	\$ 2.20	\$ 22.00 <i>X</i>
	Front Bumper Side Brkt RH <i>XIV</i>	1		\$ 35.00 <i>X</i>
	Front Bumper Grille RH ?	1		\$ 93.45 <i>X</i>
	SUB TOTAL			\$ 631.55
	LESS 20%			\$ 126.31
	TOTAL SPARE PARTS			\$ 505.24
	<u>Labour Charge</u>			
	Panel Beating		350	\$ 400.00
	Spray Painting		150	\$ 300.00
	TOTAL LABOUR			\$ 700.00
	ESTIMATE TOTAL			\$ 1,205.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

T=600 *2 day 3* *LKS* *P/P*
22/2/23
33 open
S. Lim

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hyundai Ioniq