

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS/TC123002961/4vvy3

se

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMW 7900at Workshop m/s HH

of \_\_\_\_\_

Insured: GBH 2521J

Policy No. \_\_\_\_\_

Claims No. D23000979MFCV


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 155k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 4 days

Res.: Yes or No

Lump Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

307J

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: LIA 53777Veh No: SMW 7900Yr Regn: 14/40/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: WEIBENZ CLA 180 c.c1332Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 29380

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WIK1183842N106244Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or okBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40 ZR18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 2 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 18/03/23D.O.I. 22/3/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Aug 18thhave video of fold10/4/23 1/5 @ 8800 inland Ben (red 22,350, 71%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 10/4/23-typist

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

2X15=315170+3155050+509858085814413733Report Format: TP

Lump Sum /+B+ (\$ 8800 )