

REF: Smf

REF:

NS/INC23002963/Sqp3

ASS. REC. BY:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspd Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: INC

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No

GIA / PR Scen: \_\_\_\_\_ Consistent? Yes or No

Est. Repairs: 2 days Rest: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN/OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time Action / Instruction

PIP = 640

Irfan finalised final fig \$640, 2 days. (Red \$1939.80, 75%)  
(No Lump Sum)

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1) Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I: (\$ 640)

Veh No: ShB 3377m

Yr Regr: 13/12/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Proace

cc 1798

Colour Yellow

AKC: Insured / Std / NI / NA

Sp. Reading 207436

T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C No: JTDKB3FU703082627

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD / Rim, or

Tyre Size: F: 175/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or Michelin

Front

Rear

R/Bal. 6 mm

R/Bal. 5 mm

L/Bal. 6 mm

L/Bal. 5 mm

D.O.A. 17/2/23

D.O.I. 22/2/23 3pm

Survey held at Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Date/Time: 22.02.2023 10:02

Page : 1

Job: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5886789

JC NO305546397

|                                                                                                                           |                                   |                               |
|---------------------------------------------------------------------------------------------------------------------------|-----------------------------------|-------------------------------|
| OWNER<br><br>CITYCAB PTE LTD<br>7010070<br>383 SIN MING DRIVE<br>Singapore SINGAPORE 575717<br>65551188<br>(R) (O)<br>(P) | REGN NO.:<br>SHB3377M             | MILEAGE                       |
|                                                                                                                           | MAKE:<br>TOYOTA                   | FUEL<br>E.....1/2.....F       |
|                                                                                                                           | MODEL<br>PRIUS HYBRID(G4A22.      | DATE/TIME IN<br>02.2023 09:35 |
|                                                                                                                           | YR OF MANU.<br>13.12.2019         | TARGET DATE                   |
|                                                                                                                           | CHASSIS CODE<br>JTDCB3FU703089627 | COMPLETION DATE/TIME:         |

JUNT CARD NO.


### JOB DESCRIPTION

Accident Date: 17.02.2023

ATURE: 3P 17.02.2023

'NO LABOR CODE  
00010 PB

DESCRIPTION  
LUMP SUM REPAIR-SHB3377M-TP



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

adgement Slip

Exit Pass

lo.: SHB3377M LIMITS

Vehicle No.: SHB3377M

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard