

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CC4/A1523002969/U493

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBL1790J

at Workshop m/s 2nd Auto

of 1/N 4967P

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 880k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C847K

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: L7A532865

Veh No: GBL1790J Yr Regn: 29/03/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Van

Make: Toyota Hiace C.C. 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 67342 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JT FHT02P 900251479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 60 Form

R: 195-R15 35

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/3/23

D.O.I. 22/03/23

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Reg 10K

27/3/23 N/S 81650 insured AM long

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: \_\_\_\_\_

: Site Insp (\$ )

: Interview (\$ )

: Tech. Invs (\$ )

: Weekend (\$ )

S + RS, SI

Photos

Others

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ )



VEHICLE NO. GBL 1790J

TOYOTA HIACE

| QTY | DESCRIPTION                            | CONDITION | REPAIRER'S ESTIMATE(S\$) |         | SURVEYOR'S ADJUSTMENT |
|-----|--|-----------|--------------------------|---------|-----------------------|
|     | <u>PARTS (LIST ITEMS)</u>              |           |                          |         |                       |
| 1   | Front bumper                           |           | 1752.00                  |         | 17X                   |
| 2   | Front bumper side brackets @98.20      |           | 196.40                   |         | 17X                   |
| 1   | Front bumper lower grille              | REFIX     | 0.00                     |         | 17X                   |
| 2   | Front bumper corner grille RH & LH     | REFIX     | 0.00                     |         | 17X                   |
| 1   | LHS Headlamp                           |           | 866.01 1420.00           |         | Che —                 |
| 1   | LHS Headlamp inner bracket             |           | 112.00                   |         | 17X                   |
| 1   | LHS side view mirror assembly          |           | 798.00                   |         | 17X                   |
| 1   | LHS Front corner panel                 |           | 672.00                   |         | 17X                   |
| 1   | LHS Front door                         |           | 1248.00                  |         | 25/30 —               |
| 1   | LHS Front door inner trim              | REFIX     | 0.00                     |         | 17X                   |
| 1   | LHS Front door moulding                |           | 172.00                   |         | 17X                   |
| 1   | LHS Front door glass run channel       |           | 112.00                   |         | 17X                   |
| 1   | LHS Front door hinges @49.00           | REFIX     | 0.00                     |         | 17X                   |
| 1   | LHS Front door lower step garnish      |           | 124.00                   |         | 17X                   |
| 1   | LHS Front door outer handle            | REFIX     | 0.00                     |         | 17X                   |
|     |  |           | 6606.40                  |         |                       |
|     |  | less      | 25%                      | 1651.60 | 25%                   |
|     |  |           |                          | 4954.80 |                       |
|     | <u>SPECIAL NETT ITEMS</u>              |           |                          |         |                       |
| 1   | LHS Front door inner trim clips        |           | 80.00                    |         | 17X                   |
| 1   | LHS Front door company address sticker |           | 120.00                   |         | 17 30                 |
| 1   | Front number plate                     | REFIX     | 0.00                     |         | 17X                   |
|     | Total Parts                            |           | 5154.80                  |         |                       |

Not Airtel  
 HK  
 22/03/23  
 2/3 \$ 1650/  
 2 days.

VEHICLE NO. GBL 1790J TOYOTA HIACE

| S/N | DESCRIPTION   | REPAIRER'S ESTIMATE (S\$) | SURVEYOR'S ADJUSTMENT |
|-----|---|---------------------------|-----------------------|
|     | <b>LABOUR</b>   |                           |                       |
| 1   | To remove the affected parts & fittings to commence repairs; replace damaged parts & components | 800.00                    | 200                   |
| 2   | To supply paint materials, expandable items & putty, respray paint on parts replaced            | 800.00                    | 200                   |
| 3   | To check electrical wiring at damage areas & focus headlamp beam                                | 150.00                    | 20                    |
| 4   | To conduct computerised wheel alignment test  | 120.00                    | 11X                   |
| 5   | To perform anti rust treatment on affected areas  | 150.00                    | 30                    |
|     | Labour Total :  | 2020.00                   |                       |
|     | <b>TOTAL (PARTS &amp; LABOUR):</b>  | <b>7174.00</b>            |                       |

**PRELIMINARY ESTIMATE**

**NOTE:** The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9- 2114.01  
 252  
 1581.50  
 30  
 450  
 2065.5  
 203  
 1652.4



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 847K    |

**Vehicle Details**

|                               |                        |
|-------------------------------|------------------------|
| Vehicle No.:                  | GBL1790J               |
| Vehicle to be Exported:       | No                     |
| Intended Deregistration Date: | 22 Mar 2023            |
| Vehicle Make:                 | TOYOTA                 |
| Vehicle Model:                | HIACE VAN TURBO 5DR MT |
| Primary Colour:               | White                  |
| Manufacturing Year:           | 2020                   |
| Engine No.:                   | 1KDB070438             |
| Chassis No.:                  | JTFHT02P900251479      |
| Maximum Power Output:         | -                      |
| Open Market Value:            | \$28,235.00            |
| Original Registration Date:   | 29 Mar 2021            |
| First Registration Date:      | 29 Mar 2021            |
| Transfer Count:               | 0                      |
| Actual ARF Paid:              | \$1,412.00             |

**Intended PARF Rebate Details**

|                               |        |
|-------------------------------|--------|
| PARF Eligibility:             | No     |
| PARF Eligibility Expiry Date: | -      |
| PARF Rebate Amount:           | \$0.00 |

**Intended COE Rebate Details**

|                             |                         |
|-----------------------------|-------------------------|
| COE Expiry Date:            | 28 Mar 2031             |
| COE Category:               | C - Goods Vehicle & Bus |
| COE Period(Years):          | 10                      |
| QP Paid:                    | \$40,999.00             |
| COE Rebate Amount:          | \$32,865.00             |
| <b>Total Rebate Amount:</b> | <b>\$32,865.00</b>      |

The information contained herein is correct as at 22 Mar 2023

OK

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

**ABWIN** 論壇

» Visit Our Profile «



Sort by Date Posted 20 results/page



Any Category

Advanced Search

C

Search

PREMIUM AD

PREMIUM AD

PREMIUM AD

PREMIUM AD

PREMIUM AD