

ASS. REC. BY:

REF: C72 / 23002974/Kcp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s EM

of _____

Insured: SMD 66699

Policy No. DMPCSNW00182152204

Claims No. SNM 23D202133/02 / TANKL


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJQ 46296 Yr Regn: 05, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AI

Make: Hyundai Avante c.c. 1591

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 207679 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM14DU41BR9U 757836

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Tovrader

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/3/23 D.O.I. 27/3/2023

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Get B2</u>
<u>26/4</u>	<u>LT Rep @ 3000 Cash (Red 3370.36, 527)</u>
<u>10/5/23</u>	<u>Re-confirmed LS \$3150 with Serena (Red 3326.20; 51%)</u>

Date/Time, File Pass to? : Prel. Report : Final Report

Date/Time, File Return to? 10/5/23-typist

Days Of Repair: 4
Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee: _____

Transportation: _____

\$ - RS. \$ _____

Fuel: _____

Others: _____

TOTAL: _____

Report Format: Merimen
Lump Sum / +B.I: (\$ 3150)



**SINGAPORE
POLICE FORCE**



T/20230321/2049

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

3 of 3

Report No. T/20230321/2049

CONTINUATION OF REPORT

Signature of Officer Recording The Report: F / SGT 2 Ang Boon Hong 
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414

Signature Of Informant: 
Date/Time: 21/03/2023 13:14
Classification Of Case:

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 547D

Vehicle Details

Vehicle No.: SJQ4629C
Vehicle to be Exported: No
Intended Deregistration Date: 28 Mar 2023
Vehicle Make: HYUNDAI
Vehicle Model: HD AVANTE 1.6 A
Primary Colour: White
Manufacturing Year: 2009
Engine No.: G4FC9U653005
Chassis No.: KMHDU41BR9U757836
Maximum Power Output: 89.7 kW (120 bhp)
Open Market Value: \$11,362.00
Original Registration Date: 13 May 2009
First Registration Date: 13 May 2009
Transfer Count: 1
Actual ARF Paid: \$11,362.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 12 May 2029
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$27,886.00
COE Rebate Amount: \$17,069.00
Total Rebate Amount: \$17,069.00

The information contained herein is correct as at 27 Mar 2023

OK

E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
 Singapore 575722
 Tel: 64560226 Fax: 64584500
 GST Reg. No: 201016308K

*Not authorized
 1/1 pm \$3000p
 Recovery after painting
 4 days*

ESTIMATE

Date : 27th March 2023

Mr **Chan Yee Leong**
 9 Sengkang Square, #03-01
 Singapore 545075

Veh No : **SIQ 4629C**
 Make/Model : **Hyundai Avante**
 Chassis No : KMHDU41BR9U757836
 Date of Acc : 20.03.23
 TP Veh No : SMD 6669G

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Boot Lid <i>985.90</i>		<i>Bus</i> \$ 1,188.40
2	2 pcs	Rear Boot Lid Hinges L/R	\$ 112.70	\$ R 225.40 X
3	1 pc	Rear Boot Lid Logo		\$ M 32.90
4	2 pcs	Rear Lamp L/R	\$ 326.20	\$ R 652.40 X
5	1 pc	Rear Bumper <i>582.20</i>		\$ CM 582.20
6	2 pcs	Rear Bumper Side Retainer L/R	\$ 42.30	\$ R 84.60 X
7	1 pc	Rear Bumper Reinforcement		\$ CM 286.20
8	4 pcs	Rear Bumper Reinforcement Bracket L/R	\$ 25.30	\$ R 101.20 X
9	2 pcs	Rear Bumper Bracket L/R	\$ 78.30	\$ CM 156.60
10	1 pc	Rear Bumper Inner Sponge <i>108.20</i>		\$ CM 485.10
11	1 pc	Rear End Panel <i>985.10</i>		\$ R 485.10
12	1 pc	Rear End Panel Top Garnish		\$ R 89.30
13	1 pc	Rear Boot Weatherstrip		\$ R 118.50
14	1 pc	Rear Exhaust Pipe		\$ R 693.80 X
				\$ 5,181.70
Less 20%				\$ 1,036.34
Parts Total :				\$ 4,145.36
Special Nett				
1	1 set	Rear Bumper Clips		\$ R 45.00
2	1 set	Reverse Sensor		\$ R 250.00 <i>200.00</i>
3	1 pc	Rear Bumper Spoiler		\$ R 450.00
Special Nett :				\$ 745.00
Labour				
1		To remove & rearrange electrical wirings, check lightings		\$ 80.00 <i>15%</i>
2		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.		\$ 400.00
3		To remove, replace exhaust silencer		\$ NA 150.00 X
4		Putty and respray painting on affected portions.		\$ 400.00
5		To remove & renew reverse sensor		\$ 250.00 <i>50%</i>
6		Rust proofing on affected portions.		\$ 100.00 <i>30%</i>
Labour Total :				\$ 1,380.00
Total Parts & Labour :				\$ 6,270.36

for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity
Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

ESTIMATE

Date : 27th March 2023

Chan Yee Leong
9 Sengkang Square, #03-01
Singapore 545075

Veh No : SJQ 4629C
Make/Model : Hyundai Avante
Chassis No : KMHDM41BR9U757836
Date of Acc : 20.03.23
TP Veh No : SMD 6669G

Qty	Description	Unit Price	Amount	Surveyor Adj
Materials				
1 pc	Rear Boot Lid		\$ 1,188.40	\$ 985.90
2 pcs	Rear Boot Lid Hinges L/R	\$ 112.70	\$ 225.40	\$ -
1 pc	Rear Boot Lid Logo		\$ 32.90	\$ 32.90
2 pcs	Rear Lamp L/R	\$ 326.20	\$ 652.40	\$ -
1 pc	Rear Bumper		\$ 582.20	\$ 582.20
2 pcs	Rear Bumper Side Retainer L/R	\$ 42.30	\$ 84.60	\$ -
1 pc	Rear Bumper Reinforcement		\$ 286.20	\$ 286.20
4 pcs	Rear Bumper Reinforcement Bracket L/R	\$ 25.30	\$ 101.20	repair
2 pcs	Rear Bumper Bracket L/R	\$ 78.30	\$ 156.60	\$ 156.60
1 pc	Rear Bumper Inner Sponge		\$ 141.40	\$ 108.10
1 pc	Rear End Panel		\$ 485.10	\$ 485.10
1 pc	Rear End Panel Top Garnish (photo)		\$ 89.30	\$ 89.30
1 pc	Rear Boot Weatherstrip		\$ 118.50	s/nett
1 pc	Rear Exhaust Pipe		\$ 693.80	repair
1 pc	Rear Boot Mechanism Lock (Supplementary) (photo) dented		\$ 168.00	\$ 168.00
			\$ 5,006.00	\$ 2,894.30
Less 20%			\$ 1,001.20	\$ 578.86
Parts Total :			\$ 4,004.80	\$ 2,315.44
Special Nett				
1 set	Rear Bumper Clips		\$ 45.00	\$ 45.00
1 set	Reverse Sensor		\$ 250.00	\$ 200.00
1 pc	Rear Bumper Spoiler		\$ 450.00	\$ 450.00
1 pc	Rear Boot Weatherstrip		\$ 118.50	\$ 59.25
Special Nett :			\$ 863.50	\$ 754.25
Labour				
To remove & rearrange electrical wirings, check lightings			\$ 80.00	\$ 15.00
To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.			\$ 500.00	\$ 400.00
To remove, replace exhaust silencer			\$ 150.00	\$ -
Putty and respray painting on affected portions.			\$ 500.00	\$ 400.00
To remove & renew reverse sensor			\$ 250.00	\$ 50.00
Rust proofing on affected portions.			\$ 100.00	\$ 30.00
Labour Total :			\$ 1,580.00	\$ 895.00
Total Parts & Labour :			\$ 6,448.30	\$ 3,964.44
			Lump Sum	\$ 3,150.00



for EM Solution Pte Ltd

quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.