

ASS. REC. BY:

REF:

CS/AWA23002980/Awy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA6033E Yr Regn: 2011 MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1798Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 112755 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD6620W305001785Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 22/03/23Survey held at YSK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rears o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AWA21/04/2023 Finalise 4/5 \$5,000.00 @ 6 days (Red \$3,919.30/44%)COE Expiry: 28/02/31

MV:

PV:

Nett:

673A.

Date/Time, File Pass to?

21/04/20231) Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)

Photo

Others

Report Form: TPInsured: 4/5 \$5,000.00

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SKA6033E
VEHICLE MODEL : TOYOTA WISH
CHASSIS NO : JTDGG20W305001785

TP AWA
Xin Yu

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Defect</i>	1	\$ 596.90	\$ 596.90
2	REAR BUMPER SIDE HOLDER <i>RH and</i>	2	\$ 35.40	\$ 70.80
3	REAR BUMPER IMPACT BRACKET <i>RH Defect</i>	2	\$ 68.40	\$ 136.20
4	REAR BUMPER REFLECTOR <i>RH Cracked</i>	2	\$ 56.20	\$ 112.40
5	REAR END PANEL <i>Defect</i>	1	\$ 542.20	\$ 542.20
6	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 286.60	\$ 286.60
7	REAR END PANEL ANTENNA SENSOR <i>New</i>	1	\$ 161.70	\$ 161.70
8	TAILLAMP <i>RH Cracked</i>	2	\$ 379.20	\$ 758.40
9	TAILGATE <i>Defect</i>	1	\$ 1,307.50	\$ 1,307.50
10	TAILGATE LOCK <i>Defect</i>	1	\$ 374.50	\$ 374.50
11	TAILGATE WEATHERSTRIPE <i>lt</i>	1	\$ 329.10	\$ 329.10
12	TAILGATE INNER TRIM BOARD <i>Defect</i>	1	\$ 485.50	\$ 485.50
13	TAILGATE LAMP <i>RH Cracked</i>	2	\$ 277.60	\$ 555.20
14	TAILGATE OUTER CHROME GARNISH <i>lt</i>	1	\$ 321.20	\$ 321.20
15	TAILGATE GLASS MOULDING <i>New</i>	1	\$ 162.10	\$ 162.10
16	TOYOTA LOGO	1	\$ 60.40	\$ 60.40
17	BORNEO MOTOR EMBLEM <i>New</i>	1	\$ 59.40	\$ 59.40
18	VALVE MATIC EMBLEM	1	\$ 58.10	\$ 58.10
19	REAR RH FENDER INNER TRIM BOARD <i>Not New</i>	1	\$ 434.20	\$ 434.20

TOTAL PRICE: \$ 6,812.40
LESS 25% \$ 1,703.10
SUB TOTAL PRICE: \$ 5,109.30

5113.70
3835.27

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
2	REVERSE SENSOR <i>Defect</i>	1 SET	\$ 280.00	\$ 280.00
3	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
5	TAILGATE CHROME MOULDING CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00
6	TAILGATE INNER TRIM BOARD CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
7	TAILGATE GLASS SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
8	REAR FENDER INNER TRIM BOARD CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00

TOTAL : \$ 530.00

380

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	820	

2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY	\$ 150.00	60	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	

TOTAL: \$ 3,280.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 5,639.30

TOTAL LABOUR COST: \$ 3,280.00

TOTAL REPAIR COST: \$ 8,919.30

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

2030

Total: 6245.27

L/S: SK

06 Apr.

SK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: