

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SKA6033E
VEHICLE MODEL : TOYOTA WISH
CHASSIS NO : JTDGG20W305001785

TP AWA.
Xin Yu

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehd</i>	1	\$ 596.90	\$ 596.90
2	REAR BUMPER SIDE HOLDER <i>RH and</i>	2	\$ 35.40	\$ 70.80
3	REAR BUMPER IMPACT BRACKET <i>RH Dehd</i>	2	\$ 68.40	\$ 136.20
4	REAR BUMPER REFLECTOR <i>RH Cracked</i>	2	\$ 56.20	\$ 112.40
5	REAR END PANEL <i>Dehd</i>	1	\$ 542.20	\$ 542.20
6	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 286.60	\$ 286.60
7	REAR END PANEL ANTENNA SENSOR <i>New</i>	1	\$ 161.70	\$ 161.70
8	TAILLAMP <i>RH Cracked</i>	2	\$ 379.20	\$ 758.40
9	TAILGATE <i>Dehd</i>	1	\$ 1,307.50	\$ 1,307.50
10	TAILGATE LOCK <i>Dehd</i>	1	\$ 374.50	\$ 374.50
11	TAILGATE WEATHERSTRIPE <i>lt</i>	1	\$ 329.10	\$ 329.10
12	TAILGATE INNER TRIM BOARD <i>Dehd</i>	1	\$ 485.50	\$ 485.50
13	TAILGATE LAMP <i>RH Cracked</i>	2	\$ 277.60	\$ 555.20
14	TAILGATE OUTER CHROME GARNISH <i>lt</i>	1	\$ 321.20	\$ 321.20
15	TAILGATE GLASS MOULDING <i>New</i>	1	\$ 162.10	\$ 162.10
16	TOYOTA LOGO <i>New</i>	1	\$ 60.40	\$ 60.40
17	BORNEO MOTOR EMBLEM <i>New</i>	1	\$ 59.40	\$ 59.40
18	VALVE MATIC EMBLEM <i>New</i>	1	\$ 58.10	\$ 58.10
19	REAR RH FENDER INNER TRIM BOARD <i>New</i>	1	\$ 434.20	\$ 434.20

5113.70
3835.27

TOTAL PRICE: \$ 6,812.40
LESS 25% \$ 1,703.10
SUB TOTAL PRICE: \$ 5,109.30

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
2	REVERSE SENSOR <i>Dehd</i>	1 SET	\$ 280.00	\$ 280.00
3	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
5	TAILGATE CHROME MOULDING CLIPS <i>New</i>	1 SET	\$ 20.00	\$ 20.00
6	TAILGATE INNER TRIM BOARD CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00
7	TAILGATE GLASS SEALANT <i>New</i>	1 SET	\$ 60.00	\$ 60.00
8	REAR FENDER INNER TRIM BOARD CLIPS <i>New</i>	1 SET	\$ 30.00	\$ 30.00

380

TOTAL : \$ 530.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	820	

2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY	\$ 150.00	60	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	

TOTAL: \$ 3,280.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 5,639.30

TOTAL LABOUR COST: \$ 3,280.00

TOTAL REPAIR COST: \$ 8,919.30

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

2030

Total: 6245.27

4/5 SK

06 Apr.

SK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: