

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BRANDON LYE I-VAN
94 JALAN KELICHAP
SINGAPORE 534298

Contact : 92785000

TAX INVOICE

Repair Code : CLM15832

Date in : 27/03/2023

Vehicle Num. : SLG400A

Model : MERCEDES BENZ E250 EXCLUSIVE (R18 LED)

Chassis/Eng# : WDD2130452A159097/27492030906041

TP Sompoo
Veron.

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repair</i>	1	1650.00	+ 1,650.00
FRONT BUMPER PARKING SENSOR <i>New</i>	4	270.00	+ 1,080.00
FRONT BUMPER PARKING SENSOR 'O' RING <i>New</i>	4	12.00	+ 48.00
FRONT BUMPER PARKING SENSOR HOLDER BRACKET <i>New</i>	4	25.00	+ 100.00
FRONT BUMPER RH FOGLAMP COVER <i>New</i>	1	125.00	+ 125.00
FRONT BUMPER RH FOGLAMP COVER OUTER CHROME MOULDING <i>New</i>	1	94.00	+ 94.00
FRONT BUMPER SIDE RETAINER L/R <i>New</i>	2	65.00	+ 130.00
FRONT RH DOOR <i>Repair</i>	1	2830.00	+ 2,830.00
FRONT RH DOOR INNER LOCK OPENER OUTER CHROME COVER <i>New</i>	1	78.10	- 78.10
FRONT RH DOOR WEATHER STRIP <i>New</i>	1	340.00	+ 340.00
FRONT RH FENDER (ALUMINIUM) <i>Dented</i>	1	1265.00	1043 1,265.00
FRONT RH FENDER INNER SHIELD COVER <i>New</i>	1	298.00	+ 298.00
FRONT RH LINKAGE <i>New</i>	1	106.00	+ 106.00
FRONT RH LOWER ARM	1	765.00	+ 765.00
FRONT RH SPORT RIM <i>cut</i>	1	950.00	780 (32?) - 950.00
FRONT RH TIE ROD END <i>New</i>	1	345.00	+ 345.00
FRONT RH WHEEL HUB BEARING <i>Dund</i>	1	678.00	480 - 678.00
REAR RH DOOR <i>Repair</i>	1	3150.00	+ 3,150.00

*** This is a computer-generated document which requires no signature.***

2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BRANDON LYE I-VAN
94 JALAN KELICHAP
SINGAPORE 534298

TAX INVOICE

Repair Code : CLM15832

Date in : 27/03/2023

Vehicle Num. : SLG400A

Model : MERCEDES BENZ E250 EXCLUSIVE (R18 LED)

Chassis/Eng# : WDD2130452A159097/27492030906041

Contact : 92785000

REAR RH DOOR WEATHER STRIP	1	340.00	x	340.00
RH ROCKER PANEL OUTER CHROME MOULDING (FRONT)	1	147.00	/	147.00
RH ROCKER PANEL OUTER CHROME MOULDING (REAR)	1	111.00	/	111.00
Subtotal before discount				14,630.10
Percentage discount 5% 10%				731.51
Sub-total 1				13,898.60
FRONT BUMPER CLIPS - SET	1	60.00	x	60.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	x	50.00
FRONT RH FENDER INNER SHIELD COVER CLIPS - SET	1	60.00	x	60.00
FRONT RH TYRE (CONTINENTAL 245/35ZR20)	1	550.00	x	550.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	x	50.00
Subtotal before discount				770.00
Percentage discount 0%				0.00
Sub-total 2				770.00
Parts-total				14,668.60

LABOUR

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

80 280.00

80 120.00

x 180.00

*** This is a computer-generated document which requires no signature.***

2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BRANDON LYE I-VAN
94 JALAN KELICHAP
SINGAPORE 534298

TAX INVOICE

Repair Code : CLM15832

Date in : 27/03/2023

Vehicle Num. : SLG400A

Model : MERCEDES BENZ E250 EXCLUSIVE (R18 LED)

Chassis/Eng# : WDD2130452A159097/27492030906041

Contact : 92785000

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

2w 1,200.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

300 1,000.00

To apply anti-rust chemical on repaired and replaced panel.

1290

30 80.00

Labour Total

2,860.00

Parts & Labour Total

17,528.60

*** This is a computer-generated document which requires no signature.***

page 3

total 3743.19
4/s. 23K.
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: