

S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate

#01-64/66 Singapore 575643

Tel : 6284 1542 / 6284 1575

Fax : 6487 5315

sthreeautomotive@gmail.com

TO :

ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SME6336L

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : LEE SEOK HOON

CONTACT :

ADDRESS :

LICENSE NO. : SLP8552U

CHASSIS NO. :

MAKE / MODEL : TOYOTA ALTIS

ENGINE NO. :

OWNER'S INSURER INCOME INSURANCE LIMITED

JOB-CODE : TP S/A :

ACCIDENT DATE : 19-Mar-23

Not Authorized
 11 Pm @ 3200h
 Recovery After Pains
 4 days

CLAIM DETAILMATERIALS

		QTY	UO-PRIC	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1	REAR BUMPER	Bu 1.00	680.00	25.00	510.00	Y	✓
2	REAR BUMPER BRACKET LH	M 1.00	72.20	25.00	54.15	Y	X
3	REAR BUMPER BRACKET RH	M 1.00	72.70	25.00	54.53	Y	X
4	REAR BUMPER REFLECTOR LH	Bu 1.00	155.60	25.00	116.70	Y	X
5	REAR BUMPER REFLECTOR RH	Bu 1.00	155.60	25.00	116.70	Y	X
6	REAR BUMPER SIDE RETAINER LH	Bu 1.00	67.10	25.00	50.33	Y	X
7	REAR BUMPER SIDE RETAINER RH	Bu 1.00	67.10	25.00	50.33	Y	X
8	REAR BUMPER REINFORCEMENT	408-20 Bu 1.00	498.00	25.00	373.50	Y	✓
9	REAR END PANEL	R 1.00	780.60	25.00	585.45	Y	X
10	REAR END PANEL INNER GARNISH	Bu 1.00	165.00	25.00	123.75	Y	X
11	TAILLAMP LH	394.50 Bu 1.00	747.00	25.00	560.25	Y	✓
12	TAILLAMP RH	Bu 1.00	747.00	25.00	560.25	Y	X
13	TAILLAMP INNER PANEL LH	M 1.00	250.00	25.00	187.50	Y	X
14	TAILLAMP INNER PANEL RH	M 1.00	250.00	25.00	187.50	Y	X
15	BOOTLID	Bu M 1.00	826.70	25.00	620.03	Y	✓
16	BOOTLID HINGE LH	M 1.00	155.20	25.00	116.40	Y	X
17	BOOTLID HINGE RH	M 1.00	155.20	25.00	116.40	Y	X
18	BOOTLID WEATHERSTRIP	Bu 1.00	198.22	25.00	148.67	Y	X
19	BOOTLID LOCK	M 1.00	149.00	25.00	111.75	Y	✓
20	BOOTLID CATCH	M 1.00	42.00	25.00	31.50	Y	X
21	BOOTLID EMBLEM - COROLLA	M 1.00	68.00	25.00	51.00	Y	✓
22	BOOTLID EMBLEM - ALTIS	M 1.00	68.00	25.00	51.00	Y	✓
25	BOOTLID LOGO	M 1.00	50.00	25.00	37.50	Y	✓
26	BOOTLID LAMP LH	379.80 Cu 1.00	529.70	25.00	397.28	Y	✓

27	BOOTLID LAMP RH	379.80	by	1.00	529.70	25.00	397.28	Y	✓
28	BOOTLID OUTER CHROME MOULDING		by	1.00	255.70	25.00	191.78	Y	X
29	BOOTLID NUMBER PLATE LAMP		by	2.00	136.80	25.00	102.60	Y	X
30	REVERSE SENSOR 2PCS WITH HOLDER		sen	1.00	780.00	25.00	585.00	Y	2000
31	KEYLESS SENSOR	P-? 185-20	c of by	1.00	680.00	25.00	510.00	Y	X
32	SPARE TYRE BOARD		by	1.00	380.00	25.00	285.00	Y	X

TOTAL (PARTS) : 9712.12 7284.09

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS(1 SET)		by	1.00	50.00	0.00	50.00	Y	✓
2	REAR END PANEL SEALANT		by	1.00	50.00	0.00	50.00	Y	X
3	REAR NUMBER PLATE		by	1.00	50.00	0.00	50.00	Y	4500
4	REAR END PANEL TOP GARNISH CLIPS (1SET)		by	1.00	50.00	0.00	50.00	Y	X
5	TAILLAMP PANEL HOLDER (2 SET)		by	1.00	50.00	0.00	50.00	Y	X
6	REVERSE CAMERA		by	1.00	380.00	0.00	380.00	Y	X
7	REAR WINDSCREEN SEALANT		by	1.00	50.00	0.00	50.00	Y	X
8	REAR WINDSCREEN INNER SEAL		by	1.00	50.00	0.00	50.00	Y	X
9	REAR WINDSCREEN CLEANER & PRIMER		by	1.00	50.00	0.00	50.00	Y	X

TOTAL (PARTS) : 780.00 780.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS			1.00	1200.00	0.00	1200.00	Y	5500
2	SPRAY PAINTING ON AFFECTED AREA			1.00	1600.00	0.00	1600.00	Y	6000
3	CHECK WIRING SYSTEM			1.00	120.00	0.00	120.00	Y	200
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS		by	1.00	120.00	0.00	120.00	Y	X
5	R&R CARPET, INNER TRIM TO ASSIST REPAIR		by	1.00	180.00	0.00	180.00	Y	X
6	R&R REVERSE SENSOR & RESETTING			1.00	120.00	0.00	120.00	Y	500
7	R&R BOOTLID COMPONENTS		by	1.00	120.00	0.00	120.00	Y	X
8	R&R REAR WINDSCREEN GLASS		by	1.00	180.00	0.00	180.00	Y	X

TOTAL (LABOUR) : 3640.00 3640.00

TOTAL PARTS & LABOUR : 11704.09

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• This resurvey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

EXCESS : : S\$ _____

NO. OF DAY : 04

RE-SURVEY : ~~BEFORE~~ // AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 24 / 3 / 23

SURVEY BY : Kennedy

CONTACT NO: _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.