

Vehicle Damage Assessment Report for [SKR6332C]

Estimate Created: 06/04/2023 09:44 by Insurlogic 5 (Insurlogic_Pte_Ltd)

Owned: 06/04/2023 09:49 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Volkswagen	Model	Polo
Engine Type			
License Plate Number	SKR6332C	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$ 3,200.00 WITH 3 WORKING
DAYS

Insurlogic 5 (06/04/2023 09:49)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
TAILLAMP O/S		1	418.80	-10.00 %	376.92
REAR BUMPER		1	1432.00	-10.00 %	1,288.80
REAR BUMPER REINFORCEMENT		1	354.70	-10.00 %	319.23
REAR BUMPER CENTRE RETAINER		1	89.10	-10.00 %	80.19
REAR NUMBER LAMP O/S		1	42.10	-10.00 %	37.89
END PANEL OUTER		1	600.80	-10.00 %	540.72

Parts Subtotal 2,643.75

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR NUMBER PLATE		1.0	40.00	0.00 %	40.00
REVERSE SENSOR		1.0	200.00	0.00 %	200.00

Materials Subtotal 240.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING & RESET	RnR	20.00	0.00 %	20.00
TUFF KOTE	RnR	30.00	0.00 %	30.00
PANEL BEATING	RnR	550.00	0.00 %	550.00
RNR REVERSE SENSOR	RnR	50.00	0.00 %	50.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	500.00	0.00 %	500.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 650.00

Paint Labor Subtotal 500.00

Labor Subtotal 1,150.00

Summary

Repair Cost 4,033.75

Discount(20 %)	(806.75)
	3,227.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,227.00