

FASTECH AUTO AUTO PTE LTD

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 23427

Date : 22.03.2023

Vehicle Num : SKR 6332C

Make/Model : VOLKSWAGEN POLO

Accident Date : 20.03.2023

Claim No : 0323-23427

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot lid <i>11</i>	\$ 1,459.70 <i>X</i>
2 pc	Rear boot lid hinge @ 226.30 <i>11</i>	\$ 452.60 <i>X</i>
1 pc	Rear boot lid inner lock <i>11</i>	\$ 180.90 <i>X</i>
1 pc	Rear boot lid inner board <i>11</i>	\$ 294.40 <i>X</i>
1 pc	Rear boot lid logo <i>11</i>	\$ 189.30 <i>X</i>
1 pc	Rear boot lid emblem <i>11</i>	\$ 68.10 <i>X</i>
1 pc	Rear boot lid emblem (Blue Motion) <i>11</i>	\$ 52.30 <i>X</i>
1 pc	Rear boot lid emblem (TSI) <i>11</i>	\$ 56.40 <i>X</i>
2 pc	Tail lamp @ 418.80 <i>N/S an o/s car</i>	\$ 837.60 <i>1 pc</i>
2 pc	Rear fender inner garnish @ 301.90 <i>11</i>	\$ 603.80 <i>X</i>
2 pc	Rear tail lamp panel @ 304.00 <i>11</i>	\$ 608.00 <i>X</i>
1 pc	Rear bumper <i>Dis</i>	\$ 1,432 1,806.20 <i>—</i>
1 pc	Rear bumper towing cover <i>11</i>	\$ 34.70 <i>X</i>
1 pc	Rear bumper reinforcement <i>Buf</i>	\$ 354.70 <i>—</i>
1 pc	Rear bumper centre retainer <i>CR</i>	\$ 89.10 <i>—</i>
2 pc	Rear bumper retain @ 49.70 <i>11</i>	\$ 99.40 <i>X</i>
2 pc	Rear bumper reflector @ 42.10 <i>N/S an o/s car</i>	\$ 84.20 <i>1 pc</i>
2 pc	Rear number lamp @ 35.60 <i>11</i>	\$ 71.20 <i>X</i>
1 pc	End panel <i>outer</i> <i>10/3014</i>	\$ 600.8 765.60 <i>—</i>
1 pc	End panel inner <i>NS</i>	\$ 517.20 <i>X</i>
1 pc	End panel garnish <i>11</i>	\$ 506.20 <i>X</i>
1 pc	Spare tyre panel cover board <i>11</i>	\$ 581.30 <i>X</i>
1 pc	Spare tyre tool tray sponge <i>11</i>	\$ 111.60 <i>X</i>
1 pc	Rear exhaust pipe <i>R</i>	\$ 1,106.30 <i>X</i>
1 pc	Rear exhaust pipe heat shield <i>11</i>	\$ 143.40 <i>X</i>
2 pc	Rear exhaust pipe mounting @ 57.20 <i>11</i>	\$ 114.40 <i>X</i>
List Item Total :		\$ 11,188.60
Discount 10% :		\$ 1,118.86
		\$ 10,069.74

not allowed here
23/3/23
1/5 \$ 3200
3 days

FASTECH AUTO AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262D

Estimate : 23427

Date : 22.03.2023

Vehicle Num : SKR 6332C

Make/Model : VOLKSWAGEN POLO

Accident Date : 20.03.2023

Claim No : 0323-23427

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>Spical Nett Item:</u>		
1 pc	Rear number plate <i>SCR</i>	\$ 45.00 <i>40</i>
1 set	Reversing sensor <i>self fuel</i>	\$ 450.00 <i>200</i>
Total Spical Nett Item		\$ 495.00
<u>Labour Charge:</u>		
To check wiring and reset fal cover		\$ 150.00 <i>20</i>
Tuff kote		\$ 250.00 <i>30</i>
To remove replace spare part and panel beating		\$ 1,200.00 <i>550</i>
To spray painting		\$ 1,000.00 <i>500</i>
Remove refix reversing sensor		\$ 150.00 <i>50</i>
Remove refix rear boot trimming etc		\$ <i>11</i> 250.00 <i>X</i>
Remove refix exhaust pipe		\$ <i>11</i> 150.00 <i>X</i>
Labour Charge Total :		\$ 3,150.00

E & O . E

Total Amount : \$ 13,714.74

FASTECH AUTO AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2837.5
102
264375
240