

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhammad Afiq Bin Mohamed Kamal

Date: 24 Mar 2023

**Preliminary Advice**

Vehicle No	: SNB3438A	Accident Date	: 21/03/2023
Make	: VOLKSWAGEN GOLF	Policy No.	: MPC22A00169800
Assignment Date	: 22/03/2023	Excess	: S\$0.00
Date of Inspection	: 23/3/2023	Est. Duration of Repair	: 5
Inspection At	:SME MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,160.10
Revised Amount	:S\$	10,358.60
Check Items (Estimated)	:S\$	3,118.50
Total	:S\$	13,477.10

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	30,845.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,155.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by part repair as there is no 2nd hand parts available

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .

According to surveyor modification on Air intake system, Front spoiler, rear spoiler and bodykit.

Exhaust system is legal, see documents uploaded.