

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 21.03.2023

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMH3215G**
MODEL : **TOYOTA C-HR**
DATE OF ACCIDENT : 18.03.2023
TIME OF ACCIDENT : 22:00 HOURS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 790.80	\$ 790.80
2	FRONT BUMPER RETAINER <i>RH Bnd</i>	2	\$ 107.40	\$ 214.80
3	FRONT BUMPER SIDE GARNISH RH <i>Not New</i>	1	\$ 86.50	\$ 86.50
4	FRONT BUMPER LOWER GRILLE <i>Not New</i>	1	\$ 468.70	\$ 468.70
5	HEADLAMP RH <i>Crack</i>	1	\$ 1,796.80	\$ 1,796.80
6	HEADLAMP LOWER BRACKET RH <i>Not New</i>	1	\$ 38.40	\$ 38.40
7	FRONT FENDER RH <i>Dented</i>	1	\$ 749.60	\$ 749.60
8	FRONT FENDER INNER GARNISH RH <i>Not New</i>	1	\$ 113.50	\$ 113.50
9	FRONT FENDER ARCED GARNISH RH <i>lit</i>	1	\$ 199.40	\$ 199.40
10	FRONT FENDER EMBLEM 'HYBRID' <i>Not New</i>	1	\$ 152.60	\$ 152.60
11	FRONT FENDER COWLING RH <i>Not New</i>	1	\$ 199.40	\$ 199.40
12	FRONT WHEEL RIM RH <i>lit</i>	1	\$ 1,580.30	\$ 1,580.30
13	FRONT STEERING RACK AND PINION <i>Not New</i>	1	\$ 1,695.40	\$ 1,695.40
14	FRONT ABS SENSOR RH <i>Not New</i>	1	\$ 480.20	\$ 480.20
15	FRONT KNUCLE ARM RH <i>Dented</i>	1	\$ 519.30	\$ 519.30
16	FRONT KNUCLE BEARING RH <i>Dented</i>	1	\$ 199.50	\$ 199.50
17	FRONT WHEEL HUP RH <i>Dented</i>	1	\$ 367.70	\$ 367.70
18	FRONT SHOCK ABSORBER RH <i>Best</i>	1	\$ 530.60	\$ 530.60
19	FRONT LOWER ARM RH <i>Best</i>	1	\$ 548.70	\$ 548.70
20	FRONT LINKAGE RH <i>Not New</i>	1	\$ 113.60	\$ 113.60
21	FRONT DOOR RH <i>Dented</i>	1	\$ 1,295.10	\$ 1,295.10
22	FRONT DOOR HINGE <i>Not New</i>	2	\$ 67.30	\$ 134.60

✓
107.40
+
+
✓
+
✓
+
+
65
✓
650.30
485
497
+

TO : ALLIANZ MOTOR CLAIMS DEPTS
 VEHICLE NO : SMH3215G
 MODEL : TOYOTA C-HR
 DATE OF ACCIDENT : 18.03.2023
 TIME OF ACCIDENT : 22:00 HOURS

23	FRONT DOOR LOWER PROTECTOR RH <i>lit</i>	1	\$ 285.90	\$ 285.90	✓
24	FRONT DOOR OUTER MOULDING RH <i>neu</i>	1	\$ 175.40	\$ 175.40	+
25	FRONT DOOR WEATHER STRIP RH <i>neu</i>	1	\$ 325.10	\$ 325.10	+
26	FRONT DOOR INNER LOCK RH <i>neu</i>	1	\$ 589.10	\$ 589.10	468
27	FRONT DOOR LOCK CATCH RH <i>neu</i>	1	\$ 24.20	\$ 24.20	+
28	FRONT DOOR INNER TRIM BOARD RH <i>auled</i>	1	\$ 1,097.10	\$ 1,097.10	586
29	FRONT DOOR POWER WINDOW MOTOR RH <i>neu</i>	1	\$ 779.10	\$ 779.10	+
30	FRONT DOOR SPEAKER RH <i>neu</i>	1	\$ 436.60	\$ 436.60	+
31	FRONT DOOR REGULATOR RH <i>neu</i>	1	\$ 248.50	\$ 248.50	✓
32	FRONT DOOR VIEW MIRROR RH <i>neu</i>	1	\$ 1,458.60	\$ 1,458.60	584
33	ROCKER PANEL RH <i>Reps</i>	1	\$ 1,253.00	\$ 1,253.00	+
34	SIDE SKIRT RH <i>lit</i>	1	\$ 609.70	\$ 609.70	+
35	REAR DOOR RH <i>Dented</i>	1	\$ 1,279.80	\$ 1,279.80	+
36	REAR DOOR LOWER GARNISH PROTECTOR RH <i>lit</i>	1	\$ 258.40	\$ 258.40	+
37	REAR DOOR OUTER MOULDING RH <i>neu</i>	1	\$ 167.30	\$ 167.30	+
38	REAR DOOR HINGE RH <i>neu</i>	2	\$ 48.90	\$ 97.80	+
39	REAR DOOR CHECKER RH <i>neu</i>	1	\$ 106.70	\$ 106.70	+
40	REAR DOOR WEATHER STRIP RH <i>neu</i>	1	\$ 319.40	\$ 319.40	+
41	REAR DOOR INNER LOCK RH <i>neu</i>	1	\$ 568.70	\$ 568.70	450
42	REAR DOOR LOCK CATCH RH <i>neu</i>	1	\$ 25.30	\$ 25.30	+
43	REAR DOOR INNER TRIM BOARD RH <i>auled</i>	1	\$ 976.40	\$ 976.40	655
44	REAR DOOR POWER WINDOW MOTOR RH <i>neu</i>	1	\$ 752.30	\$ 752.30	+
45	REAR DOOR SPEAKER RH <i>neu</i>	1	\$ 214.70	\$ 214.70	+
46	REAR FENDER RH <i>Reps</i>	1	\$ 986.50	\$ 986.50	+
47	REAR FENDER ARCED GARNISH RH <i>lit</i>	1	\$ 194.60	\$ 194.60	+
48	REAR WHEEL RIM RH <i>neu</i>	1	\$ 1,580.30	\$ 1,580.30	+
49	REAR ABS SENSOR RH	1	\$ 256.40	\$ 256.40	+
50	REAR LOWER ARM RH	1	\$ 542.30	\$ 542.30	+
51	REAR UPPER ARM RH	1	\$ 625.40	\$ 625.40	+
52	REAR SWING ARM RH	1	\$ 594.70	\$ 594.70	+
53	REAR SHOCK ABSORBER RH	1	\$ 530.60	\$ 530.60	+
54	REAR LINKAGE RH	1	\$ 101.40	\$ 101.40	+

TOTAL PRICE \$ 29,736.80

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMH3215G**
 MODEL : **TOYOTA C-HR**
 DATE OF ACCIDENT : 18.03.2023
 TIME OF ACCIDENT : 22:00 HOURS

1555640 S.N: 650.
 11667.25

LESS 25% \$ 7,434.20
 SUB TOTAL PRICE \$ 22,302.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	FRONT FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
3	FRONT FENDER ARCED GARNISH CLIP LH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
4	WHEEL TYRE RH <i>new</i>	2	\$ 450.00	\$ 900.00 <i>x.</i>
5	SIDE SKIRT RH CLIP <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	FRONT DOOR OUTER MOULDING CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
7	FRONT DOOR TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
8	SIDE SKIRT CLIP RH(SET) <i>Repeated new</i>	1	\$ 80.00	\$ 80.00 <i>x.</i>
9	REAR DOOR LOWER GARNISH PROTECTOR CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
10	REAR DOOR TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
11	REAR FENDER SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
12	REAR FENDER ARCED GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
13	BRAKE OIL <i>not nec</i>	1	\$ 30.00	\$ 30.00 <i>x.</i>

180 TOTAL \$ 1,600.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,200.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x.
4	TUFF COAT	\$ 250.00	80
5	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
6	WIRING CHECK	\$ 180.00	30

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMH3215G**
 MODEL : **TOYOTA C-HR**
 DATE OF ACCIDENT : 18.03.2023
 TIME OF ACCIDENT : 22:00 HOURS

7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	220
8	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	120
9	REMOVE & REFIX AUDIO SPEAKER	\$ 100.00	x
10	RESET ABS LIGHT	\$ 350.00	x
11	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	60
12	TRANSFER REAR DOOR MECHANISM	\$ 80.00	60
13	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	x
14	FOUR WHEEL ALIGNMENT	\$ 120.00	80
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2450

TOTAL \$ 7,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 23,902.60
 TOTAL LABOUR COST : \$ 7,440.00
 TOTAL REPAIR COST : \$ 31,342.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP: 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
 2/5 08 Days.

total: 11947

4/5 11950

11950