

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0264/2023/EQ
DATE : 13-Mar-23
WIP : 10913

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/3/2023

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Attn: Motor Claims Dept

OWNER'S NAME : MR TAY TECK HWEE
ADDRESS : 68 CHOA CHU KANG AVENUE 5
#01-16
SINGAPORE 688195
TELEPHONE : HP +65 96831506
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPG23000116
VEHICLE NO : **SDP 1811 M**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 28/1/2021
ENGINE NO : CZD C23835
CHASSIS NO : WAUZZZF32M1064797
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Mar-23
PLACE OF ACCIDENT : TOWARDS PENJURU ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDP 1811 M - FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$	900.00	
2	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$	580.00	
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	1,000.00	
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FAN AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,700.00	
5	TO CARRY OUT VACCUM AND REGAS FOR R1234YF.	S/N \$	1,300.00	
6	TO REMOVE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT, FRONT AND REAR SEAT BELTS.	S/N \$	2,900.00	
TOTAL LABOUR CHARGES - FRONT		:	\$ 8,380.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDP 1811 M - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER. RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,400.00	
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$ 3,300.00	
TOTAL LABOUR CHARGES - FRONT		: \$ 17,080.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDP 1811 M - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR ASSY.	S/N \$	580.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY. INSPECT FOR DAMAGES.	S/N \$	580.00	
3	TO RENEW REAR WINDSCREEN AND BOTH REAR 1/4 GLASS.	S/N \$	1,000.00	
4	TO INSTALL SOLAR FILM ON NEW GLASS.	S/N \$	800.00	
5	TO CARRY OUT WATER SEEPAGE TEST.	S/N \$	300.00	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECCESARY.	S/N \$	1,500.00	
TOTAL LABOUR CHARGES - REAR		:	\$ 4,760.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDP 1811 M - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE FRONT AND REAR SEATS, HAT TRAY, SPEAKER TRIM, ABCD PILLAR TRIMS, ROOF LINING, LIGHTS, CURTAIN AIR BAGS, CONTROLS, SENSORS AND CARPET. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	3,200.00	
8	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	S/N \$	500.00	
9	TO REMOVE REAR EXHAUST SILENCER, REAR SUSPENSION ASSY AND FUEL STORAGE TANK. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	3,600.00	
10	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER.	S/N \$	2,500.00	
11	TO DISMANTLE REAR BUMPER, REAR LID AND RHS REAR DOOR. CUT OUT AND WELD BOTH REAR FENDERS, RHS REAR FENDER REINFORCEMENTS AND CONNECTING PLATES, REAR END PANELLING, SPARE WHEEL WELL, RHS REAR CHASSIS FRAME, AND ROOF PANEL. TO REALIGN WHOLE REAR SUB-STRUCTURE TO SPECIFICATION OF ORIGIN. RENEW DAMAGED PANELS. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	33,300.00	
12	TO RESPRAY REAR BUMPER, REAR LID, WHEEL ARCH TRIMS, RHS REAR DOOR, BOTH REAR FENDERS, INNER PANELS, SPARE WHEEL WELL, CHASSIS FRAME, ROOF PANEL AND REINFORCEMENTS. TO CARRY OUT COROCOAT TREATMENT AND JOINT SEALER WORKS ON ROOF CHANNEL, DRAIN PANELS, END PANELLING, ENTRANCE CHANNEL STONECHIP TREATMENT AND BASE PRIMER WORK.	\$	13,000.00	
TOTAL LABOUR CHARGES - REAR		:	\$ 56,100.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDP 1811 M - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RENEW LHS FRONT AND RHS REAR RIMS. CARRY OUT WHEEL ALIGNMENT.	S/N \$	420.00	
14	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	584.00	
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 78,944.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER - UPPER / LOWER	1	\$ 3,016.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 458.00	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 140.00	
4	FRONT BUMPER CONNECTING PIECE	1	\$ 171.00	
5	FRONT BUMPER TRIM	1	\$ 421.00	
6	FRONT BUMPER GRILLE - CENTER	1	\$ 256.00	
7	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 62.00	
8	FRONT BUMPER LOWER GRILLE COVER PLATE	1	\$ 61.00	
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 224.00	
10	FRONT BUMPER SPOILER	1	\$ 900.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 362.00	
12	FRONT BUMPER TRIM - LH / RH	2	\$ 386.00	
13	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 31.00	
14	RADIATOR GRILLE	1	\$ 2,262.00	
15	RADIATOR GRILLE COVER	1	\$ 288.00	
16	RADIATOR GRILLE STRIKER PLATE	1	\$ 288.00	
17	RADIATOR GRILLE COVER CAP	1	\$ 242.00	
18	RADIATOR GRILLE BRACKET	1	\$ 51.00	
19	FRONT "360" CAMERA	1	\$ 1,326.00	
20	FRONT BUMPER WIRING SET	1	\$ 643.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 11,588.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,030.00	
22	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00	
23	FRONT BUMPER FOAM FILLER PIECE	1	\$ 121.00	
24	HORN BRACKET - LH	1	\$ 26.00	
25	HORN HIGH TONE - LH	1	\$ 157.00	
26	FRONT FENDER - LH	1	\$ 1,530.00	
27	FRONT FENDER BRACE - LH	1	\$ 104.00	
28	FRONT WHEEL HOUSING LINER - LH	1	\$ 281.00	
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
30	FRONT WHEEL COVER - LH / RH	2	\$ 1,200.00	
31	HEADLIGHT - LH / RH	2	\$ 12,610.00	
32	HEADLIGHT POWER MODULE	1	\$ 876.00	
33	HEADLIGHT HEAT SINK	1	\$ 924.00	
34	HEADLIGHT MOUNTING - LH	1	\$ 140.00	
35	LIFT CYLINDER - LH	1	\$ 244.00	
36	LIFT CYLINDER HOSE	1	\$ 96.00	
37	LOCK CARRIER	1	\$ 1,497.00	
38	RADIATOR AIR GUIDE - LH	1	\$ 47.00	
39	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 106.00	
40	A/C CONDENSER	1	\$ 641.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 21,781.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - FRONT**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	A/C CONDENSER SEAL RING	1	\$ 13.00	
42	A/C CONDENSER SEAL RING	1	\$ 14.00	
43	ADDITIONAL RADIATOR	1	\$ 990.00	
44	RADIATOR	1	\$ 1,099.00	
45	RADIATOR RUBBER BUSH - UPPER	2	\$ 92.00	
46	RADIATOR FAN WITH FAN RING	1	\$ 1,650.00	
47	FRONT NUMBER PLATE	S/N	\$ 100.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 37,327.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,839.00	
2	REAR DAMPING - LH / RH	2	\$ 46.00	
3	REAR BUMPER SPOILER	1	\$ 540.00	
4	REAR BUMPER GRILLE - LH / RH	2	\$ 360.00	
5	REAR PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 60.00	
6	REAR BUMPER ADAPTER - RH	1	\$ 101.00	
7	REAR BUMPER CROSS REINFORCEMENT - CENTER	1	\$ 114.00	
8	REAR BUMPER BRACKET	1	\$ 57.00	
9	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 491.00	
10	REAR TAILGATE OPENING SENSOR LINE	1	\$ 230.00	
11	REAR AERIAL KEY ACCESS	1	\$ 81.00	
12	REAR SHOCK ABSORBER	1	\$ 100.00	
13	REAR BUMPER REINFORCEMENT BEAM	1	\$ 736.00	
14	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 68.00	
15	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 150.00	
16	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	
17	REAR PARKING AID SEAL RING	4	\$ 11.00	
18	REAR BUMPER WIRING SET	1	\$ 452.00	
19	REAR BUMPER REFLECTOR - LH / RH	2	\$ 98.00	
20	REAR LID	1	\$ 3,946.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 10,023.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID HINGE - LH / RH	2	\$ 350.00	
22	REAR LID LOCK	1	\$ 310.00	
23	REAR LID BONNET LOCK COVER	1	\$ 14.00	
24	REAR LID SERVMOTOR	1	\$ 328.00	
25	REAR LID BOWDEN CABLE	1	\$ 45.00	
26	REAR LID STRIKER PLATE	1	\$ 86.00	
27	REAR SIDE PANEL FRAME BRACKET - LH / RH	2	\$ 109.00	
28	REAR LID BRACKET - LH / RH	2	\$ 109.00	
29	REAR LID DRIVE UNIT - LH / RH	2	\$ 4,304.00	
30	REAR LID FLAP GASKET	1	\$ 242.00	
31	REAR LID BALANCE WEIGHT	1	\$ 710.00	
32	REAR LID LOCK ACTUATOR CAMERA PUSHBUTTON	1	\$ 1,569.00	
33	REAR OUTER TAIL LIGHT - LH / RH	2	\$ 2,182.00	
34	REAR OUTER TAIL LIGHT TRIM - LH / RH	2	\$ 72.00	
35	REAR INNER TAIL LIGHT - LH / RH	2	\$ 2,182.00	
36	REAR INNER TAIL LIGHT TRIM - LH / RH	2	\$ 72.00	
37	REAR ADDITIONAL BRAKE LIGHT	1	\$ 198.00	
38	REAR ADDITIONAL BRAKE LIGHT ADAPTER CABLE LOOM	1	\$ 111.00	
39	REAR LICENCE PLATE LIGHT - LH / RH	2	\$ 119.00	
40	PACKING ADHESIVE	1	\$ 22.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 13,134.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	AUDI EMBLEM	1	\$ 152.00	
42	"Q3" INSCRIPTION	1	\$ 110.00	
43	REAR WINDOW	1	\$ 1,126.00	
44	WINDOW PRIMER	1	\$ 24.00	
45	REAR SPOILER - LH / RH	2	\$ 496.00	
46	REAR LID SPOILER	1	\$ 2,438.00	
47	REAR WHEEL COVER - LH / RH	2	\$ 1,200.00	
48	REAR SIDE PANEL - LH / RH	2	\$ 8,256.00	
49	REAR CROSS PANEL	1	\$ 471.00	
50	REAR CROSS PANEL REINFORCEMENT	1	\$ 768.00	
51	REAR CROSS PANEL CONNECTING PLATE - LH / RH	2	\$ 102.00	
52	REAR BOTTOM PLATE	1	\$ 2,106.00	
53	REAR BOTTOM PLATE - RH	1	\$ 314.00	
54	REAR CROSS MEMBER	1	\$ 222.00	
55	REAR EXHAUST SYSTEM MOUNT BRACKET - LOWER	1	\$ 73.00	
56	REAR SIDE MEMBER - RH	1	\$ 1,896.00	
57	REAR WHEEL HOUSING INNER PART - RH	1	\$ 1,200.00	
58	REAR FUEL FILLER FLAP	1	\$ 250.00	
59	REAR FUEL INSERT	1	\$ 114.00	
60	REAR THROTTLE CONTROL ELEMENT	1	\$ 100.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 21,418.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REAR FUEL DRAIN HOSE	1	\$ 21.00	
62	REAR WHEEL HOUSING LINER	1	\$ 283.00	
63	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	
64	REAR INNER SIDE PANEL - RH	1	\$ 1,247.00	
65	REAR C-PILLAR REINFORCEMENT - RH	1	\$ 826.00	
66	REAR WHEEL HOUSING LINER INNER PART - RH	1	\$ 1,038.00	
67	REAR ROOF	1	\$ 3,456.00	
68	REAR ROOF REINFORCEMENT	1	\$ 187.00	
69	REAR ROOF 2K PANE ADHESIVE SET	1	\$ 111.00	
70	REAR ROOF 1-PACK ADHESIVE	1	\$ 81.00	
71	REAR ROOF HOSE - LH / RH	2	\$ 52.00	
72	ROOF PRIMER	1	\$ 24.00	
73	REAR ROOF FRAME - FRONT	1	\$ 305.00	
74	REAR ROOF FRAME - REAR	1	\$ 122.00	
75	REAR ROOF 2K PANE ADHESIVE SET - LH / RH	2	\$ 221.00	
76	REAR ROOF HOSE	4	\$ 103.00	
77	REAR CROSS PANEL TRIM	1	\$ 485.00	
78	REAR LUGGAGE COMPARTMENT FLOOR COVERING	1	\$ 1,052.00	
79	REAR SPARE WHEEL WELL SUPPORT ELEMENT	1	\$ 269.00	
80	REAR LUGGAGE COMPARTMENT TRIM - RH	1	\$ 1,068.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 11,056.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	REAR LID TRIM PANEL - LOWER	1	\$ 573.00	
82	REAR TAIL LIGHT COVER - LH / RH	2	\$ 192.00	
83	REAR LID TRIM PANEL - UPPER CENTRE	1	\$ 126.00	
84	REAR LID TRIM PANEL - LH / RH	2	\$ 328.00	
85	REAR LUGGAGE COMPARTMENT COVER	1	\$ 518.00	
86	REAR GUIDE - RH	1	\$ 86.00	
87	REAR C-PILLAR TRIM - RH	1	\$ 187.00	
88	REAR QUARTER WINDOW - LH / RH	2	\$ 1,448.00	
89	WINDOW PRIMER	2	\$ 47.00	
90	THREE-POINT SEAT BELT - LH / RH	2	\$ 2,054.00	
91	SEAT BELT HEIGHT ADJUSTER - LH / RH	2	\$ 393.00	
92	THREE-POINT SEAT BELT - LH	1	\$ 576.00	
93	REAR FELT STRIPS	1	\$ 27.00	
94	THREE-POINT SEAT BELT - RH	1	\$ 576.00	
95	REAR FELT STRIPS	1	\$ 27.00	
96	AIRBAG CONTROL UNIT	1	\$ 1,742.00	
97	AIRBAG CRASH SENSOR	4	\$ 1,842.00	
98	REAR SUPPORT FRAME	1	\$ 1,932.00	
99	REAR TRACK ROD	1	\$ 129.00	
100	REAR BRACKET - RH	1	\$ 160.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 12,963.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	REAR AXLE GUIDE - RH	1	\$ 584.00	
102	REAR LOWER CONTROL ARM	1	\$ 569.00	
103	REAR UPPER CONTROL ARM	1	\$ 302.00	
104	REAR WHEEL BEARING HOUSING - RH	1	\$ 786.00	
105	REAR WHEELHUB WITH BEARING	1	\$ 558.00	
106	REAR GAS SHOCK ABSORBER	1	\$ 308.00	
107	REAR ALUMINIUM RIM - LH / RH	2	\$ 2,970.00	
108	REAR DOOR - RH	1	\$ 3,203.00	
109	REAR DOOR OUTER SEAL - RH	1	\$ 159.00	
110	REAR DOOR CATCH - RH	1	\$ 141.00	
111	REAR DOOR INNER SEAL	1	\$ 226.00	
112	REAR SILL PANEL SEAL - RH	1	\$ 159.00	
113	REAR DOOR LOCK - RH	1	\$ 815.00	
114	REAR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	1	\$ 324.00	
115	REAR DOOR COVER - RH	1	\$ 389.00	
116	ACRYLIC SEALER	S/N	\$ 720.00	
117	CAVITY WAX	S/N	\$ 560.00	
118	STONECHIP	S/N	\$ 540.00	
119	METAL FILLER POWDER	S/N	\$ 560.00	
120	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 14,073.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDP 1811 M - REAR**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	1/4 GLASS SEALANT	S/N	\$ 200.00	
122	SUNDRIES		\$ 2,000.00	
TOTAL SPARE PARTS - FRONT & REAR		:	\$ 122,194.00	
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 78,944.00	
GRAND TOTAL		:	\$ 201,138.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT