

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 23 Mar 2023

**Preliminary Advice**

Vehicle No	: SDP1811M	Accident Date	: 06/03/2023
Make	: AUDI Q3 SPORTBACK	Policy No.	: -
Assignment Date	: 22/03/2023	Excess	: S\$0.00
Date of Inspection	: 23/03/2023	Est. Duration of Repair	: 32
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	193,638.00
Revised Amount	:S\$	91,602.50
Check Items (Estimated)	:S\$	28,794.00
Total	:S\$	120,396.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	64,824.00
Salvage Value	:S\$	
Margin for Repair	:S\$	93,176.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Pending repair cost from repairer.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.