



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2304905

INV Date 01/08/2023

Reference CC4/LPC23002995/Kya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 7710T

Insured Veh. XD 9116K

Claim No. 23/23/23/VC05/027147

Policy No. Z23VC05015557

Accident Date 17/03/2023

Inspection Date 27/03/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC23002995/Kya3q2	
			Date: 01/08/2023	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 9116K	Veh. Inspected	SMC 7710T
	Policy No.	Z23VC05015557	Coverage (\$)	0.00
	Claim No.	23/23/23/VC05/027147	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	22/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS IS300 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTHBA1D2605075570	Colour	METALLIC DARK BLUE
	Odometer	46222 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	7 mm
	L/H Front Tyre	225/45 R17	PIRELLI	7 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	7 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/03/2023	Inspection Date	27/03/2023
	Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 7710T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER FASCIA	CRACKED	1,150.50	1,150.50
1	REAR O/S BUMPER SIDE RETAINER	DISTORTED	155.10	155.10
1	REAR O/S SPORT RIM	DENTED	3,038.20	2,980.10
1	REAR O/S DOOR PROTECTOR TAPE	NOT NECESSARY	51.50	-
	LESS 10% DISCOUNT		-439.53	-428.57
			3,955.77	3,857.13
	<u>LABOUR</u>			
	TO TRANSFER SPORT RIM & BALANCE.		50.00	20.00
	TO PUTTY AND SPRAY REPLACED PARTS.		700.00	450.00
	TO REMOVE ,CUT -OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS.		600.00	450.00
			1,350.00	920.00
	GRAND TOTAL		5,305.77	4,777.13
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CC4/LPC23002995/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 7710T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 7710T

RE-INSPECTION

