

C

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : XD9116K
Accident Date : 17-Mar-2023

No. : 06790

Date : 22-Mar-2023

Our Ref : 023062 (LONPAC) / CHAN

PAGE : 1

SHIH CHI FONG
13 LENTOR PLACE
Singapore 789000

*Not Withheld
Running After Pain
C/ly &*

ESTIMATED COST OF REPAIR FOR LEXUS IS300 SMC7710T

1 pc	Rear bumper fascia	cm	1,150.50	✓
1 pc	Rear o/s bumper side retainer	DIY	155.10	✓
1 pc	Rear o/s sport rim	DIY	3,038.20	✓
1 pc	Rear o/s door protector tape	DIY	51.50	X
			4,395.30	
		Less 10% :	439.53	

3,955.77

To transfer sport rim & balance

50.00 *20%*

To putty and spray replaced parts

700.00 *45%*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *45%*

Total : S\$ 5,305.77

Singapore Dollars Five Thousand Three Hundred
and Five and Cents Seventy Seven Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: