

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internati	onale Des Experts E		000/0	SAI23001245	
		N INSURANCE COMPANY		Ref:	<del>000/0/12000</del>	-	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	IAL TOWER		Date:	00/02/2023	21/03/2023	
				Code:	GAI		
	Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	YP 8713T	Veh. Inspected	d	PC 3893P		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	CLMOMVC000004304	Excess (\$)		0.00		
	Assign From	SHERY WONG	Assign Date		06/02/2020	21/03/2023	
		Vehicle Part	iculars & Condit	ion			
	Make & Model		c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	-	Steering				
	Brakes		Modification				
	General						
		Condi	tions of Tyres				
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
•		Descript	ion of Damages				
	General Information						
	Accident Date	06/02/2023	Inspection Date	te	07/02/2023		
	Survey held at	ANN JOO MOTOR PL					
		BLK 176 SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721					
ia.		Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						