



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002996/Tvy3e2 Date: 28/04/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	SKJ 80K	Veh. Inspected	SLT 7369T	
Policy No.	C0123886	Coverage (\$)	0.00	
Claim No.	AVS22/0808	Excess (\$)	0.00	
Assign From	ESTHER CHEAH	Assign Date	21/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA C-HR	c.c	1797	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZYX102080088	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	MICHELIN	5 mm	
L/H Front Tyre	225/50 R18	MICHELIN	5 mm	
R/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
L/H Rear Tyre	225/50 R18	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/03/2022	Inspection Date	28/03/2023	
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 09 NOV 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	