



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: RAJESWARY			Ref: CS3/INC23001026/Wqy3m4-1 Date: 24/04/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 7164K	Veh. Inspected	SMP 5607D
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1207770-002	Excess (\$)	0.00
	Assign From		Assign Date	20/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	BMW 216I GRAN TOURER	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WBA6V120305N83078	Colour	WHITE
	Odometer	66091 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	CONTINENTAL	7 mm
	L/H Front Tyre	225/50 R17	CONTINENTAL	7 mm
	R/H Rear Tyre	225/50 R17	CONTINENTAL	7 mm
	L/H Rear Tyre	225/50 R17	CONTINENTAL	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/01/2023	Inspection Date	01/02/2023
	Survey held at	BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 451875		
	Repairer	SHIFTER AUTO GARAGE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	