

SALES QUOTATION
30057070

Customer Ref No : 8202902905
RFQ Ref No : 5000630131
Customer : 9AMB/92FMD MOS
Ship To : KRANJI CAMP 2, BLK 807, #01-18
151 CHOA CHU KANG WAY
SINGAPORE 688248

Date : 02 May 2023
Delivery Period : 21
Subcon Delivery Period : 0

Vehicle No : MID34029
Description : Specified Repair

PP NO. 4002097637
JA
MOI IF 20328820
PP LEVEL 1
LEVEL 2 - NIL

33FMD - Refaxed 26/5/26

Dear Sir,

We hereby submit the quote for the repair of the above equipment in accordance to the job description attached in the following page.

1. Labour with baseload		Sub-total :	1,809.94
Description	Rate (\$\$)	Mhrs	Amount(\$\$)
Basic MHR (BMR)	82.27	22.00	1,809.94 ✓
2. Assessment Fee		Sub-total :	658.12
DF-Equip charged under Basic			658.12
3. Materials		Sub-total :	32.35
Material Services			32.35
4. General Service		Sub-total :	273.40
Tow Svc Wheeled (< 3 Ton)			273.40
Grand Total :			2,773.81 ✓

Price quoted in Singapore Dollar(SGD) are subjected to prevailing GST rate.

Validity of Quotation: 30 Days

Yours faithfully

BER/Not Approved/Rejected* by:
*(Delete where applicable)

Name: S Manogaran
Date: 02.05.2023

X _____
Name:
Date:

This is a computer generated form. No Signature required.

ST Engineering Land MRO & Services Pte Ltd
249 Jalan Boon Lay, Singapore 619523
T: (65) 66603698, F: (65) 63165371
(Regn. No.: 199506881H)

www.stengg.com

SALES QUOTATION

30057070



PARTICULARS OF VEHICLE / COMPONENT

Vehicle No	: ME34029	Chassis/Hull No	: 907W207445	SWD Reading	: 0.00
Engt Comp NSA	: 0320814436	Engine/Comp	: NA	Engine HRS	: 0.00
Engt Comp Desc	: FORD EVEREST OUV (TRUCK, UTILITY, FORD EVEREST, FFR			Speedo Reading	: 640.00
	: FORD)				

CUSTOMER REFERENCE

Date Of RFQ	: 21 April 2023	Unit	: Sg Gedong camp	Prepared By	: Abdul Ghani Awi
Customer No	: NA	MOMR No	: 8202902905		
Zonal	: 92FMD (MOS)	Job No	: 4055272		

Scope Of Work & Labour

Task ID	S/N	Description	Work Done	Quoted MHR	MHR Type	Remarks
5		SPECIFIED REPAIRS				
10	1	Body RH rear fender panel dented	REP	18.00	BMR	
15	1.1	Renew "Do Not Pull" sticker	RPL			
20	1.2	Remove and refit exterior cable duct, RH rear fender inner trim, reverse sensor unit and PDB assembly to assist in above repair	REP			
45	2	Spray paint on all above accident repaired areas	REP & RPL	4.00	BMR	
50						
55	3	Diagnostic fee for Equipment charged under BMR			DFA4	
60						
65		TOWING SERVICES				
70	4	Collect vehicle from Sg Gedong camp, return to same location			TOWL3T	
75		POC - ME3 Yeo TL 98555012				
80						
85		REMARKS (INFO)				
90		ERP ID admitted				
95		Both: blindspot mirrors present				
100		Fire extinguisher not present				
105		Rifle rack present				
110		Spare wheel present				
115		Rear ladder present				
120		Engine able to start				
125		PDB present x02				
130		PDB batteries present x02				
135		Rear signaller backrest cushion present				
140		RH rear pillar inner trim torn				
145		Exterior cable duct cover scratched and screw missing				
150		RH rear antenna mount scratched				
155						
			Grand Total	22.00	BMR	

Note : Items that cannot be checked by QA will be written as NA

LEGEND: REP - REPAIR, RPL - REPLACE, INFO - INFORMATION ONLY, T/A - TIME ADJUSTED

ST Engineering Land MRO & Services Pte Ltd

249 Jalan Boon Lay, Singapore 619523

T: (65) 66603698, F: (65) 63166371

(Regn. No.: 199506881H)

www.stengg.com

SALES QUOTATION

30057070



Materials

Task ID	Item Number	Description	Unit Price(S\$)	UOM	Qty	Sea/Air Freight	Batch	Class	Total Price(S\$)
15	OUV-DNPS	DO NOT PULL STICKER	6.35	EA	1.00			006	6.35
45	NTV	P3 GREEN PAINT	26.00	L	1.00				26.00
Sub-total									32.35

Assessment Fee

Type	Description	Unit Price(S\$)	Mark Up	Total Price(S\$)
SS-DFA4	DF-Equip charged under Basic	658.12		658.12
Sub-total				658.12

General Services

Type	Description	Unit Price(S\$)	Qty	Total Price(S\$)
SS-TOWL3T	Tow Svc Wheeled (< 3 Ton)	136.70	2.00	273.40
Sub-total				273.40

Note : Items that cannot be checked by QA will be written as NA

LEGEND: REP - REPAIR, RPL - REPLACE, INFO - INFORMATION ONLY, T/A - TIME ADJUSTED

Material Class:

001-SS MPL PP, 002-SS MPL Non-PP, 003-SS MPL Agency, 004-SS MPL Value Added, 005-SS Non MPL PP, 006-SS Non MPL Non PP, 007-SS Non MPL Agency, 008-SS Non MPL Value Added, 009-SS Non MPL Non-PP(Supplier Contract), 201-SDDA SS MPL PP, 202-SDDA SS MPL Non-PP, 203-SDDA SS MPL Agency, 204-SDDA SS MPL Value Added, 205-SDDA SS Non MPL PP, 206-SDDA SS Non MPL Non-PP, 207-SDDA SS Non MPL Agency, 208-SDDA SS Non MPL Value Added

ST Engineering Land MRO & Services Pte Ltd

249 Jalan Boon Lay, Singapore 619523

T: (65) 66603698, F: (65) 63165371

(Regn. No.: 199506881H)

www.stengg.com