

REC. BY:

REF:

012 / 230030101kp

C

Keneth

ENT

SHD 363L

03 16

Date:

Estimated Cost:

Car / M.Cycle / Bus / Van / Lorry

P / WS / TP RES / OD RES / EVA / INV / MV

Truck / Tractor or

Inspected Vehicle No:

(A)

Workshop name:

Trans Cab

Renault Latitude

1995

M. White / Mr

Registration

591090

VFI ABL 15AUC 002727

Condition: Good / Fair / Poor / Burnt

Engine: In order / Jammed / Leaked / Burnt or

Transmission: In order / Jammed / Leaked / Burnt or

Wheels: R / L / S / R / L / STD A / R / L or

Carlander 215/60R16

R. Finns

EXNOVA / GY / FS / LIZA / MIC / OHE / PLS

TOKO or

Pre-accident Condition

Repair: The veh had commenced its repair at the time of inspection.

Balance Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / R / Seen: Consistent? : Yes or No

Est. Repair: 02 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / EV / REP. / 24 HRS

Date: Person Contacted:

Vehicle:

9 mm
20/13/23
7
7
21/3/23

Pages: Fnt / Rear / O/S / N/S / U/C / Photo

N/S FM

Chassis frame / Body Structure affected

Date / Time Action / Instruction

27/3 / 11:00 @ 1700 Cash

Date/Time / Return to?

Prell. Report

Date/Time / Return to?

Final Report

Date/Time / Return to?

Add. Fee:

Repair:

No. of Trip:

Survey Fee:

Report format:

Lump Sum / I.B.I. (\$)

(\$)

(\$)

(\$)

(\$)

Transportation

(\$ - RS, \$)

Fuels

Others

TOTAL

Not Authored
11/10/1700h

Trans-cab Auto Services Pte Ltd

AAD2303-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD363L

Vehicle No.:

SHD363L

Chassis No.:

VF1ABL15AUC282719

Co UEN:

200303878K

Vehicle Make:

21 MAR 2023

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

20/03/23

Third Party Insurer :

GBL 4390K/China

Date of Registration :

17/5/2016

PART	LIST		
1 BUMPER COVER FRT	\$ Bu	747.20	✓
1 BUMPER RETAINER FRT LH	\$ Di	101.40	✓
1 HEADLAMP LH	\$ Pa	743.60	X
1 FENDER PANEL FRT LH	\$ B	437.10	✓
1 WHEELARCH FRT LH	\$ Pa	191.40	X
1 AIR CLEANER BOX	\$ m	464.20	↑
	\$	2,684.90	
	10% \$	268.49	
	\$	2,416.41	

Special Nett			
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00	X
1 RIM	\$	Pa 350.00	X
1 TYRE	\$	Pa 300.00	X
1 BUMPER CLIP FRT	\$	na 85.00	GBL
1 FENDER LINER CLIP	\$	na 65.00	X
TOTAL	\$	830.00	
TOTAL PARTS	\$	3,246.41	

LABOUR			
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	401

