

Not Authored
11/2/2023

AAD2303-

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD363L

Vehicle No.:	SHD363L
Chassis No.:	VF1ABL15AUC282719
Co UEN:	200303878K
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	20/03/23
Third Party Insurer :	GBL 4390K / China
Date of Registration :	17/5/2016

21 MAR 2023

PART	LIST	
1 BUMPER COVER FRT	\$ Bu	747.20 ✓
1 BUMPER RETAINER FRT LH	\$ Di	101.40 ✓
1 HEADLAMP LH	\$ Su	743.60 X
1 FENDER PANEL FRT LH	\$ B	437.10 ✓
1 WHEELARCH FRT LH	\$ Su	191.40 X
1 AIR CLEANER BOX	\$ m	464.20 ✓
	\$	2,684.90
	10% \$	268.49
	\$	2,416.41

Special Nett		
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00 X
1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00 X
1 RIM	\$	Su 350.00 X
1 TYRE	\$	Su 300.00 X
1 BUMPER CLIP FRT	\$	na 85.00 ✓
1 FENDER LINER CLIP	\$	na 65.00 X
	TOTAL \$	830.00
	TOTAL PARTS \$	3,246.41

LABOUR		
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 ✓✓
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 ✓✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD363L

AAD2303-

To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>30/</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>15/</i>
TOTAL	\$	6,560.00	
Over All Total	\$	12,222.82	

**(LUMP SUM)
Repair Days**

~~03~~ DAYS

2 days

For Official Use

Prepared By : *Menneth*
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: