

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: LIBERTY	DATE	: 21-Mar-23
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKZ8384Y		
MODEL	: HONDA VEZEL 1.5X CVT		
CHASSIS NO	:		
ACCIDENT DETAILS	DATE : 20-Mar-23 TIME : 13:00PM		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 820.00	\$ 820.00
2	FRONT BUMPER SIDE RETAINER <i>LH Rnd</i>	2	\$ 55.40	\$ 110.80 <i>55.40</i>
3	FRONT BUMPER REINFORCEMENT BAR <i>Dented</i>	1	\$ 420.00	\$ <u>420.00</u>
4	FRONT BUMPER LOWER LID <i>Del</i>	1	\$ 422.30	\$ <u>422.30</u>
5	FRONT BUMPER FOGLAMP <i>new</i>	1	\$ 230.50	\$ 230.50
6	FRONT BUMPER FOGLAMP HOUSING <i>Crackd</i>	1	\$ 155.90	\$ <u>155.90</u>
7	HID HEADLAMP <i>Crackd</i>	1	\$ 1,955.30	\$ 1,955.30
8	HEADLAMP LOWER BRACKET <i>Crackd</i>	1	\$ 74.00	\$ 74.00
9	FRONT GRILLE BASE <i>new</i>	1	\$ 420.00	\$ 420.00
10	FRONT FENDER <i>Distorted</i>	1	\$ 560.20	\$ 560.20
11	FRONT FENDER INNER COWLING <i>Del</i>	1	\$ 168.00	\$ 168.00
12	FRONT WHEEL HOUSE PANEL <i>Repair</i>	1	\$ 988.50	\$ 988.50
13	WHEEL ARCH <i>Del</i>	1	\$ 180.00	\$ 180.00
14	FRONT SHOCK ABSORBER	1	\$ 398.40	\$ 398.40
15	FRONT WHEEL HUP	1	\$ 268.00	\$ 268.00
16	FRONT WHEEL HUP BEARING	1	\$ 264.00	\$ 264.00
17	FRONT KNUCKLE ARM	1	\$ 385.00	\$ 385.00
18	FRONT LOWER ARM	1	\$ 412.00	\$ 412.00
19	FRONT DOOR LH <i>Repair</i>	1	\$ 1,533.50	\$ 1,533.50

TOTAL PRICE

\$9,766.40

LESS 20% \$ 1,953.28
 SUB TOTAL PRICE \$7,813.12

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	HEADLAMP CLIPS(SET) <i>NW</i>	1	\$ 20.00	\$ 20.00
2	HEADLAMP PROTECTION STICKER <i>NW</i>	1	\$ 100.00	\$ 100.00
3	FRONT BUMPER CLIPS(SET) <i>NW</i>	1	\$ 20.00	\$ 20.00
4	FRONT BUMPER LOWER LID CLIPS(SET) <i>NW</i>	1	\$ 20.00	\$ 20.00
5	FRONT FENDER INNER COWLING RH (CLIPS) <i>NW</i>	1	\$ 20.00	\$ 20.00
6	TYRE RIM (1 SET) <i>NW</i>	1	\$ 1,200.00	\$ 1,200.00
7	WHEEL TYRE <i>NW</i>	1	\$ 350.00	\$ 350.00
8	WHEEL ARCH CLIP(SET) <i>NW</i>	1	\$ 20.00	\$ 20.00

TOTAL \$1,750.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	500	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800	
3	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO	\$ 180.00	X	
4	WIRING CHECK	\$ 150.00	30	
5	TO REFOCUS HEADLAMP BEAM	\$ 250.00	X	
6	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 250.00	X	
7	FOUR WHEEL ALIGNMENT	\$ 250.00	80	
8	TO REMOVE AND RFEFIX FRONT DOOR MECHANISM	\$ 140.00	X	

TOTAL \$4,020.00

ESTIMATE REPORT

TOTAL PARTS COST : \$9,563.12
 TOTAL LABOUR COST : \$4,020.00
 TOTAL REPAIR COST : \$13,583.12

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
 2/5 22/03/23.
 05 Days