

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003021/RQP3Q2**Date:** 18/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00267462200

Claimant Vehicle No : SLA3986M **Insured Vehicle No :** SNH7042A

Date of Loss: 15/03/2023 Nature of Claim: TP Claim No: SNM23D202015/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA3986M**

Make & Model: SUBARU BRZ, 2.0 RWD 6 (A) Engine No: FA20A867373

Reg. Date: 29/02/2016 (Man. Year: 2016) Chassis No: JF1ZC6K81GG009635

Colour: White Odometer: 75696 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,809.10	8,570.60	4,238.50	33.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,035.00	6,680.00	4,355.00	39.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,844.10	15,250.60	8,593.50	36.04
+ GST 8.00/8.00% (S\$)	1,907.53	1,220.05	687.48	36.04
Nett Amount (S\$)	25,751.63	16,470.65	9,280.98	36.04

INSPECTION

Date of Assignment: 23/03/2023

Date Inspected: 23/03/2023 Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 13.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2023)
Parts:	M1-COUPE	SUBARU BRZ 2.0 RWD 6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3986M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ARM ASSY F RH	Bent	370.00 FS	*370.00 FS
2	1		*STRUT COMPL F RH	Bent	425.50 FS	*425.50 FS
3	2		*MOUNT STRUT F LH/RH	Bent	168.00 FS	*84.00 FS
4	1		*STABLIZER LINK	Not Necessary	88.80 FS	*- FS
5	1		*TYRE VALVE	Necessary	25.50 FS	*25.50 FS
6	3		*DISC WHEEL AL 17 BRZ	Scratched	4,500.00 FS	*4,500.00 FS
7	1		*HOUSING -F AXLE RH	Bent	266.40 FS	*266.40 FS
8	1		*PNL SD OUT QTR RPRH	Repair	888.00 FS	*- FS
9	1		*FENDER F RPR RH	Bent	277.50 FS	*277.50 FS
10	1		*HOOD COMPLETE -FRONT	Not Necessary	906.50 FS	*- FS
11	1		*BUMPER FACE F	Deformed	610.50 FS	*610.50 FS
12	1		*BUMPER FACE R	Not Necessary	610.50 FS	*- FS
13	1		*ENERGY ABS -FRT BMBR	Not Necessary	85.10 FS	*- FS
14	1		*BRKT CORNER F RH	Necessary	48.10 FS	*48.10 FS
15	1		*BRKT CORNER F LH	Not Necessary	48.10 FS	*- FS
16	1		*BRKT -R BMBR CRNR RH	Necessary	22.20 FS	*22.20 FS
17	1		*BRKT -R BMBR CRNR LH	Not Necessary	22.20 FS	*- FS
18	1		*BRKT -REAR BMBR SD RH	Not Necessary	15.90 FS	*- FS
19	1		*BRKT -REAR BMBR SD LH	Not Necessary	15.90 FS	*- FS
20	1		*BRKT -SD TURN LAMP RH	Cracked	11.10 FS	*11.10 FS
21	1		*BRKT -SD TURN LAMP LH	Not Necessary	11.10 FS	*- FS
22	1		*BRKT BUMP R LWR	Not Necessary	14.80 FS	*- FS
23	1		*BACK BEAM COMPLETE -FRONT	Not Necessary	370.00 FS	*- FS
24	1		*BACK BEAM COMPLETE -REAR	Not Necessary	296.00 FS	*- FS
25	1		*COVER -REAR BMBR RH	Not Necessary	6.70 FS	*- FS
26	1		*COVER -REAR BMBR LH	Not Necessary	6.70 FS	*- FS
27	1		*MUD GUARD ASSY F RH	Deformed	111.00 FS	*111.00 FS
28	1		*WDW GL ASSY R QTR RH	Not Necessary	518.00 FS	*- FS
29	1		*DAM RUBBER	Not Necessary	22.20 FS	*- FS
30	1		*R VIEW MIR UNIT RHR	Cracked	499.50 FS	*499.50 FS
31	1		*COVER -CAP OUT MIRROR, RH	Cut	66.60 FS	*66.60 FS
32	1		*CAP -MIRROR STAY ,RIGHT	Missing	19.10 FS	*19.10 FS
33	1		*GARNISH -FRONT FENDER ,RIGHT	Not Necessary	148.00 FS	*- FS
34	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
35	1		*HUB COMPL F AXLE	Bent	307.10 FS	*307.10 FS
36	1		*PNL COMPL DR F RH	Bent	832.50 FS	*832.50 FS
37	1		*ORNAMENT F	Necessary	74.00 FS	*74.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **12,809.10** **8,570.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT HOOD ,RH FENDER ,FRT BUMPER ,RH DOOR ,RH QUARTER PANEL ,REAR BUMPER	New	4,200.00	3,000.00
2	RESPRAY FRT HOOD ,FRT BUMPER RH FENDER ,RH DOOR ,RH QUARTER PANEL ,REAR BUMPER ,RH SIDE MIRROR	New	4,200.00	2,080.00
3	TRANSFER /BALANCE TYRE/RIMS	New	150.00	150.00
4	4 WHEEL ALIGNMENT	New	200.00	200.00
5	DISMANTLE & REIF UNDERCARRIAGE (FRONT) TO FACILITATE REPAIR	New	300.00	300.00
6	TRANSFER RH DOOR MECHANISM	New	200.00	150.00
7	TO CONDUCT WATER SEEPAGE	New	100.00	30.00
8	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	New	150.00	150.00
9	TO REMOVE & REFIX FUEL TANK	New	200.00	0.00
10	TO CONDUCT ANTI-RUST COATING	New	580.00	290.00
11	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	New	100.00	0.00
12	TO SUPPLY & INSTALL RH QUARTER GLASS TINTED FILM	New	145.00	0.00
13	TO CONDUCT FRONT LIGHTING TEST	New	50.00	50.00
14	FAULT DIAGNOSTIC (RESET)	New	280.00	280.00
15	REMOVE & RENEW RH QUARTER GLASS	New	180.00	0.00
Gross Labour Cost (S\$)			11,035.00	6,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >