

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0086/2023
DATE : 22-MAR-2023

CHINA TAIPING INSURANCE (SINGAPORE)PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : WONG SOON TECK
ADDRESS : 41 SELETAR GREEN VIEW
S(805175)
TELEPHONE NO : 9682 4110

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100454220 AIG
VEHICLE NO : SLA3986M
MODEL CODE : ZC6DKE8
MODEL/YEAR : SUBARU BRZ 2.0 RWD 6MT
ENGINE NO : FA20A867373
CHASSIS NO : JF1ZC6K81GG009635
MILEAGE : 1 KM
DATE IN : 22/03/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 22/03/2023

Print Date : 22/03/2023
Print Time : 12:02:13

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA3986M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST CHINA TAIPING-SNH7042A		
2	ZZ/001	DOA:15/MAR/2023 TIME:0800 HRS LOCATION:ROADSIDE OUTSIDE UNIT 41 SELETAR GREEN V		
3	ZZ/002	REPLACE FRT HOOD,RH FENDER,FRT BUMPER,RH DOOR, RH QUARTER PANEL,REAR BUMPER	4200.00	
4	ZZ/003	RESPRAY FRT HOOD,FRT BUMPER,RH FENDER,RH DOOR,RH QUARTER PANEL,REAR BUMPER,RH SIDE MIRROR	4200.00	
5	ZZ/004	TRANSFER/BALANCE TYRE/RIMS - 3PCS	150.00	
6	ZZ/005	4 WHEEL ALIGNMENT	200.00	
7	ZZ/006	DISMENTLE & REIF UNDERCARRIAGE (FRONT) TO FACILITATE REPAIR	300.00	
8	ZZ/007	TRANSFER RH DOOR MECHANISM	200.00	
9	ZZ/008	TO CONDUCT WATER SEEPAGE	100.00	
10	ZZ/009	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	
11	ZZ/011	TO REMOVE & REFIX FUEL TANK	200.00	
12	ZZ/012	TO CONDUCT ANTI-RUST COATING	580.00	
13	ZZ/013	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	
14	ZZ/014	TO SUPPLY & INSTALL RH QUARTER GLASS TINTED FILM	145.00	
15	ZZ/015	TO CONDUCT FRONT LIGHTING TEST	50.00	
16	ZZ/016	FAULT DIAGNOSTIC (RESET)	280.00	
17	ZZ/017	SUNDRIES	100.00	
18	ZZ/10	REMOVE & RENEW RH QUARTER GLASS	180.00	
TOTAL LABOUR CHARGES			11135.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA3986M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	ARM ASSY F RH	20202CA000			370.00	
2	STRUT COMPL F RH	20310CA120			425.50	
3	MOUNT STRUT F LH/RH	20320AA112			168.00	
4	STABLIZER LINK	20420CA000			88.80	
5	TYRE VALVE	23142GA040			25.50	
6	DISC WHEEL AL 17 BRZ *3PCS	28111CA010			4500.00	
7	HOUSING-F AXLE RH	28313CA000			266.40	
8	PNL SD OUT QTR RPRH	51439CA0009P			888.00	
9	FENDER F RPR RH	57129CA0209P			277.50	
10	HOOD COMPLETE-FRONT	57229CA0009P			906.50	
11	BUMPER FACE F	57702CA160			610.50	
12	BUMPER FACE R (57704CA011 & 57756CA020NN)	57704CA010			610.50	
13	ENERGY ABS-FRT BMBR	57705CA000			85.10	
14	BRKT CORNER F RH	57707CA002			48.10	
15	BRKT CORNER F LH	57707CA012			48.10	
16	BRKT-R BMBR CRNR RH	57707CA080			22.20	
17	BRKT-R BMBR CRNR LH	57707CA090			22.20	
18	BRKT-REAR BMBR SD RH	57707CA100			15.90	
19	BRKT-REAR BMBR SD LH	57707CA110			15.90	
20	BRKT-SD TURN LAMP RH	57707CA130			11.10	
21	BRKT-SD TURN LAMP LH	57707CA140			11.10	
22	BRKT BUMP R LWR	57707FJ201			14.80	
23	BACK BEAM COMPLETE-FRONT	57711CA0009P			370.00	
24	BACK BEAM COMPLETE-REAR	57711CA0209P			296.00	
25	COVER-REAR BMBR RH	57731CA100			6.70	

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	COVER-REAR BMBR LH	57731CA110			6.70	
27	MUD GUARD ASSY F RH	59110CA001			111.00	
28	WDW GL ASSY R QTR RH	65209CA000			518.00	
29	DAM RUBBER	65245CA000			22.20	
30	R VIEW MIR UNIT RHR	91036CA006			499.50	
31	COVER-CAP OUT MIRROR,RH	91059CA000			66.60	
32	CAP-MIRROR STAY,RIGHT	91067CA000			19.10	
33	GARNISH-FRONT FENDER,RIGHT	91112CA060NN			148.00	
SUB TOTAL			0.00	0.00	11495.50	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	11495.50	0.00
OVERALL TOTAL			11495.50			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA3986M

TOTAL LABOUR CHARGES	11135.00
TOTAL SPARE PARTS CHARGES	11495.50
GRAND TOTAL	22630.50 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.