

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SMR 7210R**

Made : Audi

Model : Q3 1.4 TFSI

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper <i>cra</i>	1	\$ 1,890.00	\$ 1,890.00
2	Rear Bumper Lower <i>cra</i>	1	\$ 540.00	\$ 540.00
3	Rear Bumper Guide Section RH <i>cra</i>	1	\$ 112.00	\$ 112.00
4	Rear Bumper Guide Section LH <i>cra</i>	1	\$ 112.00	\$ 112.00
5	Rear Bumper Tow Cover <i>X nn</i>	1	\$ 48.00	\$ 48.00
6	Rear Bumper Reflector RH <i>cra</i>	1	\$ 49.00	\$ 49.00
7	Rear Bumper Reflector LH <i>cra</i>	1	\$ 49.00	\$ 49.00
8	Rear Bumper Parking Aid Sensor <i>faulty -</i>	24	\$ 244.00	\$ 976.00
9	Rear Bumper Parking Aid Seal Ring <i>X nn</i>	4	\$ 1.50	\$ 6.00
10	Rear Bumper Reinforcement Beam <i>X nn</i>	1	\$ 736.00	\$ 736.00
11	Rear Fender Wheel Arch Garnish RH <i>X nn</i>	1	\$ 302.00	\$ 302.00
12	Rear Fender Wheel Arch Garnish LH <i>X nn</i>	1	\$ 302.00	\$ 302.00
13	Rear Tailgate <i>X nn</i>	1	\$ 3,985.00	\$ 3,985.00
14	Rear Tailgate Emblem <i>X nn</i>	1	\$ 138.00	\$ 138.00
15	Rear Tailgate "Q3" Emblem <i>X nn</i>	1	\$ 99.00	\$ 99.00
16	Rear Tailgate Lock <i>X nn</i>	1	\$ 310.00	\$ 310.00
17	Rear Tailgate Lock Striker <i>X nn</i>	1	\$ 78.00	\$ 78.00
18	Rear Tailgate Weatherstrip <i>X nn</i>	1	\$ 298.00	\$ 298.00
19	Rear Tailgate Inner Trim Board <i>X nn</i>	1	\$ 573.00	\$ 573.00
20	Rear Tailgate Taillamp Assembly RH <i>X nn</i>	1	\$ 1,091.00	\$ 1,091.00
21	Rear Tailgate Taillamp Assembly LH <i>X nn</i>	1	\$ 1,091.00	\$ 1,091.00
22	Rear Taillamp Assembly RH <i>X nn</i>	1	\$ 1,091.00	\$ 1,091.00
23	Rear Taillamp Assembly LH <i>X nn</i>	1	\$ 1,091.00	\$ 1,091.00
24	Rear End Panel Upper <i>dent</i>	1	\$ 348.00	\$ 348.00
25	Rear End Panel Lower <i>X nn</i>	1	\$ 768.00	\$ 768.00
26	Rear End Panel Top Garnish <i>X nn 5350</i>	1	\$ 225.00	\$ 225.00
27	Rear Fender Wheel Arch Garnish RH <i>X nn</i>	1	\$ 283.00	\$ 283.00
28	Rear Fender Wheel Arch Garnish LH <i>X nn</i>	1	\$ 283.00	\$ 283.00
29	Rear Silencer <i>X nn</i>	1	\$ 1,271.00	\$ 1,271.00
30	Dual Clip <i>X nn</i>	1	\$ 96.00	\$ 96.00
31	Retaining Ring - Centre/RH <i>X nn</i>	2	\$ 20.00	\$ 40.00
32	Retaining Ring Bracket LH <i>X nn</i>	1	\$ 87.00	\$ 87.00

1390✓

✓

✓

✓

✓

✓

488✓

✓

33	Exhaust Tailpipe Chrome Tip	X nn	1	\$	268.00	\$	268.00
34	Front Bumper	cra -	1	\$	1,285.00	\$	1,285.00
35	Front Bumper Closing Element RH	X nn	1	\$	66.00	\$	66.00
36	Front Bumper Closing Element LH	X nn	1	\$	66.00	\$	66.00
37	Front Bumper Grille Centre	cra X nn	1	\$	242.00	\$	242.00
38	Front Bumper Grille RH	X nn	1	\$	124.00	\$	124.00
39	Front Bumper Grille LH	X nn	1	\$	124.00	\$	124.00
40	Front Bumper Closing Element Lower	X nn	1	\$	212.00	\$	212.00
41	Front Bumper Lower Spoiler	X nn	1	\$	426.00	\$	426.00
42	Front Bumper Air Guide Grille RH	X nn	1	\$	171.00	\$	171.00
43	Front Bumper Air Guide Grille LH	X nn	1	\$	171.00	\$	171.00
44	Radiator Grille	BA cra -	1	\$	1,594.00	\$	1,594.00
45	Radiator Grille Striker Plate	X nn	1	\$	271.00	\$	271.00
46	Front Bumper Foam Filler Piece	13 ✓	1	\$	114.00	\$	114.00
47	Front Bumper Reinforcement Beam	X nn	1	\$	974.00	\$	974.00
48	Front Bumper Guide Section RH	X nn	1	\$	43.00	\$	43.00
49	Front Bumper Guide Section LH	X nn	1	\$	43.00	\$	43.00
50	Front Bumper Top Cover	X nn	1	\$	137.00	\$	137.00
51	Caution Sticker	X nn	1	\$	16.00	\$	16.00
52	Air Cond Sticker	X nn	1	\$	9.00	\$	9.00
53	Front Parking Sensor	X X nn	4	\$	244.00	\$	976.00
54	Front Parking Sensor Seal Ring	X nn	4	\$	1.50	\$	6.00
55	Front Headlamp Assembly RH	cra -	1	\$	5,952.00	\$	5,952.00
56	Front Headlamp Assembly LH	cra -	1	\$	5,952.00	\$	5,952.00
57	Front Headlamp Mounting RH	X nn	1	\$	132.00	\$	132.00
58	Front Headlamp Mounting LH	X nn	1	\$	132.00	\$	132.00
59	Lift Cylinder RH	X nn	1	\$	231.00	\$	231.00
60	Lift Cylinder LH	X nn	1	\$	231.00	\$	231.00
61	Lift Cylinder Hose RH	X nn	1	\$	92.00	\$	92.00
62	Lift Cylinder Hose LH	X nn	1	\$	92.00	\$	92.00
63	Radiator Air Guide RH	X nn	1	\$	43.00	\$	43.00
64	Radiator Air Guide LH	X nn	1	\$	43.00	\$	43.00
65	Radiator Air Guide Upper	X nn	1	\$	48.00	\$	48.00
66	Front Fender Wheel Arch Garnish RH	X nn	1	\$	283.00	\$	283.00
67	Front Fender Wheel Arch Garnish LH	X nn	1	\$	283.00	\$	283.00
68	Front Fender Inner Cowling RH	X nn	1	\$	260.00	\$	260.00
69	Front Fender Inner Cowling LH	X nn	1	\$	260.00	\$	260.00

987✓

1275✓

✓

✓

17,254.00 5350
-5% -5%
16,391.30 5082.50

Parts Sub Total :	\$	39,740.00
Discount	\$	1,987.00
PARTS TOTAL :	\$	37,753.00

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	X nn	1	\$ 50.00
2	Front Number Plate	X nn	1	\$ 50.00
3	Rear Bumper Clips - Set	BA X nn	1	\$ 50.00

4	Rear Bumper Lower Clips - Set X nn	1	\$	50.00	\$	50.00
5	Rear Taillamp Clips - Set X nn	1	\$	50.00	\$	50.00
6	Rear End Panel Top Garnish Clips - Set X nn	1	\$	50.00	\$	50.00
7	Rear Fender Wheel Arch Garnish Clips - Set X nn	1	\$	60.00	\$	60.00
8	Front Bumper Clips - Set X nn	1	\$	50.00	\$	50.00
9	Radiator Grille Clips - Set X nn	1	\$	50.00	\$	50.00
10	Front Fender Wheel Arch Garnish Clips - Set X nn	1	\$	60.00	\$	60.00
11	Front Fender Inner Cowling Clips - Set X nn	1	\$	80.00	\$	80.00
12	Rear Tailgate Sealant X nn	1	\$	150.00	\$	150.00
13	Rear End Panel Sealant X nn	1	\$	150.00	\$	150.00
14	Rear Tailgate Windscreen Glass Sealant X nn	1	\$	150.00	\$	150.00
15	Rear Tailgate Reverse Camera X nn	1	\$	500.00	\$	500.00

SPECIAL NETT TOTAL : \$ 1,550.00

60

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts (Front)	\$ 1,200.00
2	To Panel Beat, Remove & Refix Parts (Rear)	\$ 1,800.00
3	To Spray Paint Affected Areas (Front)	\$ 1,200.00
4	To Spray Paint Affected Areas (Rear)	\$ 1,800.00
5	Wiring & Bulb Check (Front)	\$ 100.00
6	Wiring & Bulb Check (Rear)	\$ 100.00
7	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 150.00
8	To Transfer Rear Tailgate Mechanism	\$ 150.00
9	To Remove & Refix Rear Tailgate Reverse Camera	\$ 150.00
10	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00
11	To Remove & Refix Front Bumper Sensor	\$ 120.00
12	To Remove & Refix Rear Exhaust Pipe	\$ 150.00
13	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00
14	To Remove & Refix Front Headlamp Control Unit & Power Module	\$ 200.00
15	To apply anti rust on affected parts	\$ 100.00
16	To Conduct Water Leak Test	\$ 100.00
17	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00

LABOUR TOTAL : \$ 8,070.00

1060

PARTS TOTAL : \$ 37,753.00

SPECIAL NETT TOTAL : \$ 1,550.00

LABOUR TOTAL : \$ 8,070.00

GRAND TOTAL : \$ 47,373.00

82m/s
L/S
2.30pm
24/3/23
Infm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17,511.30

6202.50

L/S - 14,009.04
= 14,000.00

L/S - 4962
= 4950