

Chew Goon Motor (Co.Reg.No:22188000C)Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Tel: 64841626 Fax: 64840465 Email: aaronm3@chewgoonmotor.com.sg;chewgoon@singnet.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	SJL3721B
Policy No:	SP2003215160-01	Date of Loss:	28/01/2023
Vehicle Reg. No.:	SJL3721B	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN YONG PHIO MRS WONG YONG PHIO	Contact No:	+6593636966
Driver:	NIGEL WONG HAN-MING		

Make/Model:	BMW 216D, 1.5 D ACTIVE TOURER LED EU6 (A)	Vehicle Reg. Date:	22/12/2017
Vehicle Colour:	Blue		
Engine No:	38045042B37C15A	Chassis No:	WBA2B32080V926096
Odometer:	0 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 10 4

Description of Accident/Loss REFER TO SKETCH PLAN.

Present Location: CHEW GOON MOTOR (AMK)

COST OF CLAIMS	Amount
Parts	4,881.70
Miscellaneous Items	0.00
Labour	610.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	5,491.70

This claim is handled by: KUEK SUE FANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2023)

Parts: M1-MPV BMW 216D 1.5 D ACTIVE TOURER LED EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Chew Goon Motor/SJL3721B/22/03/2023 09:58

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper	0.00	0.00	*950.00 F CUT
2	12		*Front Bumper Clips	0.00	0.00	*18.00 F NEC
3	1		*Front Bumper Emblem	0.00	0.00	*62.00 F NEC
4	1		*Front Bumper Center Air Grille	0.00	0.00	*130.00 F CUT LH
5	1		*Front Bumper Sensor	0.00	0.00	*120.00 F ?
6	1		*Front Bumper Number Plate Base Holder	0.00	0.00	*62.00 F DT
7	1		*Front Bumper Sponge	0.00	0.00	*95.00 F X NN
8	1		*Front Bumper Reinforcement	0.00	0.00	*420.00 F X NN
9	1		*Front Bumper Beam	0.00	0.00	*130.00 F X NN
10	1		*Front Bumper Fog Lamp LH	0.00	0.00	*190.00 F X NN
11	1		*Front Bumper Fog Lamp Cover LH	0.00	0.00	*80.00 F ?
12	1		*Front Bumper Inner Air Duct (Plastic)	0.00	0.00	*170.00 F CUT
13	2		*Grilles	0.00	0.00	*170.00 F ?
14	1		*Headlamp LH	0.00	0.00	*1,800.00 F ?
15	1		*Front Number Plate	0	0.00	*45.00 FS DT

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,442.00
+ Margin on L,N Items 10.00% (S\$)	439.70
Total Parts (S\$)	4,881.70

Chew Goon Motor/SJL3721B/22/03/2023 09:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultant is hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To Conduct Electrical Check, Focus Headlamp	New	30.00
2	Labour Charge - Panel Beating, Repairing Headlamp Panel, Support & Part Replacement	New	380.00
3	To Respray Affected Areas	New	200.00
Gross Labour Cost (\$\$)			610.00

Chew Goon Motor/SJL3721B/22/03/2023 09:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 4 DAYS

- NOT AUTHORISE

- EXCESS \$ 0

- P/P OR T/S REPAIR?

- SURVEY BY EDWARD, TEL 62563561

- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: