

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 13 Apr 2023

**Preliminary Advice**

Vehicle No	: SJL3721B	Accident Date	: 28/01/2023
Make	: BMW 216D	Policy No.	: SP2003215160-01
Assignment Date	: 23/03/2023	Excess	: S\$0.00
Date of Inspection	: 23/03/2023	Est. Duration of Repair	: 4
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,491.70
Revised Amount	:S\$	5,020.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,020.90
Lump Sum Repair	:S\$	4,000.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	81,000.00
COE / PARF Rebate	:S\$	38,574.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,426.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Kindly approve repair cost \$4,000.00 and 4 repair days