

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23003033/KVY3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : PC8130A**Insured Vehicle No :** XE1318S

Date of Loss: 15/03/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PC8130A**

Make & Model: GOLDEN DRAGON XML6113J98, 6.7 D (M)

Engine No: ISB67E6C29022334508

Reg. Date: 10/09/2019 (Man. Year: 2019)

Chassis No: LL3AGCDH7KA031429

Colour: Multi-colour

Odometer: 158173 km

Engine Capacity: 6690 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5

Rear Tyre Size: 11 R22.5 (D)

Front Left Side: Michelin 7 mm

Rear Left Side: Giti 8/8 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Giti 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,300.00	800.00	38.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,100.00	1,300.00	800.00	38.10

INSPECTION

Date of Assignment: 23/03/2023

Date Inspected: 28/03/2023 Inspected At:

Serve You Motor Service (HQ)
BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
#01-265
Singapore 569536

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Apr 2023)	
Parts:	N/A	GOLDEN DRAGON XML6113J98 6.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8130A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR	New	600.00	300.00
2	SUPPLY AND PROVIDE NECESSARY MULTI-PURPOSE MATERIAL/ITEMS TO RESPRAY ON ACCIDENT DAMAGED PORTION SPRAY PAINT MULTI-PURPOSE	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			2,100.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >