

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/H5B23003037/4p93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMQ6321R

at Workshop m/s Spadwick

of _____

Insured: SFJ 7118A

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £ 60k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 2279 31879

Veh No: SMQ6321R Yr Regn: 20/10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Toyota wish c.c 1798

Colour: black A/C: Insured / Std / NI / NA

Sp. Reading: 255604 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDG420W50J005456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/452R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6

R/Bal. mm

L/Bal. 6 mm

D.O.A. 21/03/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Day 146

4/4/23 2/5 @ 1100 in hand brief

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

SPEEDWERKZ PRIVATE LIMITED

1KAKI BUKIT AVENUE 6 ,#01-73, AUTOBAY, SINGAPORE 417883

TEL : 96195936 / info@speedwerkz.biz

VEHICLE No : SMQ 6321R

1PC	REAR DOOR O/S	<i>R</i>	\$1,415.20	X
1PC	REAR DOOR LOWER CHROME MOULDING O/S	<i>der</i>	\$281.30	✓
1PC	REAR FENDER O/S	<i>R</i>	\$1,105.20	X
1PC	ROCKER PANEL GARNISH O/S	<i>cut/trim</i>	\$766.10	✓
			\$3,567.80	
			LESS 25%	\$2,675.85

TO CHECK WIRING	<i>11</i>	\$50.00	<i>4</i>
TO SPRAY RUST PROOFING	<i>11</i>	\$50.00	<i>4</i>
TO CONDUCT WHEEL ALIGNMENT	<i>11</i>	\$100.00	<i>X</i>
LABOUR FOR PANEL BEATING & REPLACE DPARTS		\$600.00	<i>200</i>
TO PUTTY & SPRAY PAINTING		\$900.00	<i>400</i>
	TOTAL	\$4,375.85	

not Allowed
der
24/3/23
2/5 @ 1100
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-1047.4
252
785.55
600
1385.55
22
1108