

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : GBG44355
VEHICLE MODEL : TOYOTA DYNA
CHASSIS NO : JTFAT35Y70K208531

T-18BC NTUC
Xiao Chen.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE BRACKET <i>Best</i>	1	\$ 160.40	\$ 160.40
2	TAILLAMP <i>LH cracked.</i>	2	\$ 255.40	\$ 510.80
3	TAILLAMP PANEL <i>Repair</i>	2	\$ 185.50	\$ 371.00
4	REAR DOOR LOWER PANEL <i>Repair</i>	1	\$ 495.90	\$ 495.90

TOTAL PRICE: \$ 1,538.10
LESS 25% \$ 384.52
SUB TOTAL PRICE: \$ 1,153.58

415.80
311.85

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00
2	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 280.00	\$ 280.00
3	REAR DOOR <i>Dented</i>	2	\$ 1,800.00	\$ 3,600.00
4	REAR DOOR INNER WOODEN BOARD <i>New</i>	2	\$ 300.00	\$ 600.00
5	REAR DOOR VERTICAL LOCK BAR <i>LH Best</i>	2	\$ 350.00	\$ 700.00
6	REAR DOOR VERTICAL LOCK BAR LOWER BRACKET <i>LH Best</i>	2	\$ 120.00	\$ 240.00
7	70KM/H STICKER <i>3 new</i>	1	\$ 15.00	\$ 15.00
8	12 PAX STICKER	1	\$ 15.00	\$ 15.00

TOTAL: \$ 5,480.00

3200.

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>500</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>500</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>40</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	

TOTAL: \$ 2,300.00

1120

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,633.58
TOTAL LABOUR COST: \$ 2,300.00
TOTAL REPAIR COST: \$ 8,933.58

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

Total: 4631.85

4/5 : 3.7K.

04 Days.

3.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: