

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Apr 2023

Preliminary Advice

Insured Vehicle No	: SMT3560X	Accident Date	: 23/03/2023
TP Vehicle No	: SFH3743G	Assignment Date	: 23/03/2023
Make	: ADIVA AD1 200	Est. Duration of Repair	: 6 days
Date of Inspection	: 24/03/2023		
Inspection At	: TWINCAR AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,741.30
Revised Amount	:S\$	5,505.03
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,505.03
Lump Sum Repair	:S\$	4,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : The above survey was conducted on a 'Without Prejudice' basis.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.