

## Vehicle Damage Assessment Report for [SFH3743G]

Estimate Created: 11/04/2023 16:38 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

Owned: 11/04/2023 16:53 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | ERGO                         | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |         |
|----------------------|----------|--------------------|---------|
| Brand                | Toyota   | Model              | Corolla |
| Engine Type          |          |                    |         |
| License Plate Number | SFH3743G | VIN (or Chassis #) |         |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$4,400.00 WITH 6 WORKING  
DAYS

Insurlogic 4 (11/04/2023 16:53)

**Parts**

| Description                         | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|-------------------------------------|-------------|-----|--------|---------------|--------|
| Bootlid                             |             | 1   | 840.00 | -25.00 %      | 630.00 |
| Bootlid 1.6 emblem                  |             | 1   | 40.10  | -25.00 %      | 30.08  |
| Bootlid Altis emblem                |             | 1   | 53.20  | -25.00 %      | 39.90  |
| Bootlid Corolla emblem              |             | 1   | 53.20  | -25.00 %      | 39.90  |
| Bootlid Logo emblem                 |             | 1   | 66.90  | -25.00 %      | 50.18  |
| Bootlid mechanism lock              |             | 1   | 121.10 | -25.00 %      | 90.83  |
| Bootlid weatherstrip                |             | 1   | 209.90 | -25.00 %      | 157.43 |
| Rear bumper                         |             | 1   | 660.80 | -25.00 %      | 495.60 |
| Rear bumper reflector<br>L/R        |             | 2   | 46.90  | -25.00 %      | 70.35  |
| Rear bumper side bracket<br>L/R     |             | 2   | 37.60  | -25.00 %      | 56.40  |
| Rear bumper sponge                  |             | 1   | 153.80 | -25.00 %      | 115.35 |
| Rear end panel                      |             | 1   | 727.70 | -25.00 %      | 545.78 |
| Rear end panel inner top<br>garnish |             | 1   | 231.60 | -25.00 %      | 173.70 |
| Rear end panel nose<br>bracket L/R  |             | 2   | 93.00  | -25.00 %      | 139.50 |
| Rear taillamp black<br>gasket L/R   |             | 2   | 29.80  | -25.00 %      | 44.70  |
| Rear taillamp L/R                   |             | 2   | 365.00 | -25.00 %      | 547.50 |
| Rear taillamp lower<br>bracket L/R  |             | 2   | 71.90  | -25.00 %      | 107.85 |

Parts Subtotal 3,335.05

**Materials**

| Description                         | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|-------------------------------------|-------------|-----|--------|---------------|--------|
| Rear bumper clips - set             |             | 1.0 | 30.00  | 0.00 %        | 30.00  |
| Rear bumper reverse<br>sensor - set |             | 1.0 | 200.00 | 0.00 %        | 200.00 |
| Rear taillamp clips L/R -<br>set    |             | 1.0 | 20.00  | 0.00 %        | 20.00  |

Materials Subtotal 250.00

**Labor****Replace/RnR**

| Description                                                   | Type | Cost  | Markup/Disc % | Price |
|---------------------------------------------------------------|------|-------|---------------|-------|
| To transfer bootlid mechanism lock outer handle<br>reflector. | RnR  | 60.00 | 0.00 %        | 60.00 |
| To checking wiring and rewire rear parking sensor.            | RnR  | 80.00 | 0.00 %        | 80.00 |

|                                                                                               |     |        |        |        |
|-----------------------------------------------------------------------------------------------|-----|--------|--------|--------|
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. | RnR | 60.00  | 0.00 % | 60.00  |
| To remove and refit rear exhaust silencer.                                                    | RnR | 60.00  | 0.00 % | 60.00  |
| Panel beating                                                                                 | RnR | 800.00 | 0.00 % | 800.00 |
| To apply anti rust chemical on repaired and replaced panel.                                   | RnR | 60.00  | 0.00 % | 60.00  |

#### Repair

| Description               | Severity | Cost | Markup/Disc % | Price |
|---------------------------|----------|------|---------------|-------|
| Rear exhaust silencer box | Medium   | 0.00 | 0.00 %        | 0.00  |

#### Paint

| Description    | Paint Type | Cost   | Markup/Disc % | Price  |
|----------------|------------|--------|---------------|--------|
| Spray painting | Full spray | 800.00 | 0.00 %        | 800.00 |

Labor Rate                      S\$ 50 / Hour

General Labor Subtotal                      1,120.00

Paint Labor Subtotal                      800.00

Labor Subtotal                      1,920.00

#### Summary

Repair Cost                      5,505.05

Discount(20 %)                      (1,101.00)

4,404.05

Excess                      (0.00)

GST(0.00 %)                      0.00

Grand Subtotal                      4,404.05