

Date: 22/03/2023

Vehicle No: SJT5372U

Model: TOYOTA VIOS E

Chassis: MR053HY9305131860-2009

Reg.Year: 2009

Third Party Insurer: ALLIANZ

Third Party Veh No: GBK4856P

Date of Accident: 22/03/2023

Estimator: TING AN

Surveyor:

*Not Withheld*  
*1/1 Sup &*  
*Recovery After Pain*  
*7 days*

## ESTIMATE

| NO.         | DESCRIPTION                          | QTY | UNIT S\$ | AMOUNT S\$       |
|-------------|--------------------------------------|-----|----------|------------------|
| 1           | REAR BOOTLID                         | 1   |          | Ry \$486.00      |
| 2           | REAR BOOTLID "TOYOTA" EMBLEM         | 1   |          | Re \$60.00       |
| 3           | REAR BOOTLID "E" EMBLEM              | 1   |          | Re \$40.00       |
| 4           | REAR BOOTLID OUTER GARNISH COVER     | 1   |          | Wage \$270.00    |
| 5           | REAR BOOTLID LOCK                    | 1   |          | Re \$130.00      |
| 6           | REAR BOOTLID HINGE LH                | 1   |          | R \$95.00        |
| 7           | REAR BOOTLID HINGE RH                | 1   |          | R \$95.00        |
| 8           | REAR BOOTLID WEATHERSTRIP            | 1   |          | Dis 120 \$210.00 |
| 9           | REAR TAIL LAMP LH                    | 1   |          | CM \$320.00      |
| 10          | REAR TAIL LAMP RH                    | 1   |          | CM \$320.00      |
| 11          | REAR TAIL LAMP BRACKET LH            | 1   |          | \$65.00          |
| 12          | REAR TAIL LAMP BRACKET RH            | 1   |          | \$65.00          |
| 13          | REAR BUMPER                          | 1   |          | Ry \$505.00      |
| 14          | REAR BUMPER SIDE BRACKET LH          | 1   |          | Dis 110 \$110.00 |
| 15          | REAR BUMPER SIDE BRACKET RH          | 1   |          | Dis 110 \$110.00 |
| 16          | REAR BUMPER REFLECTOR LH             | 1   |          | Rm \$128.00      |
| 17          | REAR BUMPER REFLECTOR RH             | 1   |          | Rm \$128.00      |
| 18          | REAR END PANEL                       | 1   |          | Ry \$645.00      |
| 19          | REAR END PANEL UPPER COVER           | 1   |          | Re \$235.00      |
| 20          | REAR FLOOR PANEL TOOLBOX FOAM TRAY   | 1   |          | Rm \$214.00      |
| 21          | REAR FLOOR PANEL TOOLBOX UPPER BOARD | 1   |          | Re \$288.00      |
| 22          | FRONT BUMPER                         | 1   |          | Re 110 \$485.00  |
| 23          | FRONT BUMPER SIDE BRACKET LH         | 1   |          | Rm \$66.00       |
| 24          | FRONT BUMPER SIDE BRACKET RH         | 1   |          | Re \$66.00       |
| 25          | FRONT BUMPER REINFORCEMENT           | 1   |          | \$382.00         |
| 26          | FRONT BUMPER LOWER GRILLE            | 1   |          | CM \$88.00       |
| 27          | FRONT HEADLAMP LH                    | 1   |          | Rm \$446.00      |
| 28          | FRONT HEADLAMP RH                    | 1   |          | Rm \$446.00      |
| SUB TOTAL   |                                      |     |          | \$6,498.00       |
| LESS 25%    |                                      |     |          | -\$1,624.50      |
| PARTS TOTAL |                                      |     |          | \$4,873.50       |

### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 22/03/2023  
 Vehicle No: SJT5372U  
 Model: TOYOTA VIOS E  
 Chassis: MR053HY9305131860-2009  
 Reg.Year: 2009

Third Party Insurer: ALLIANZ  
 Third Party Veh No: GBK4856P  
 Date of Accident: 22/03/2023  
 Estimator: TING AN  
 Surveyor:

| NO.       | SPECIAL NETT                     | QTY | UNIT S\$ | AMOUNT S\$                        |
|-----------|----------------------------------|-----|----------|-----------------------------------|
| 1         | REAR BUMPER CLIPS                | 1   |          | <i>me</i> \$50.00 ✓               |
| 2         | REAR BUMPER REVERSE SENSOR       | 1   |          | <i>Phon</i> \$300.00 <i>200sn</i> |
| 3         | REAR NUMBER PLATE & HOLDER       | 1   |          | <i>Eyat</i> \$50.00 <i>45sn</i>   |
| 4         | REAR END PANEL JOINT SEALANT     | 1   |          | <i>me</i> \$100.00 <i>30sn</i>    |
| 5         | REAR END PANEL UPPER COVER CLIPS | 1   |          | <i>me</i> \$40.00 —               |
| 6         | FRONT BUMPER CLIPS               | 1   |          | <i>me</i> \$50.00 ✓               |
| 7         | FRONT NUMBER PLATE & HOLDER      | 1   |          | <i>CM</i> \$50.00 <i>45sn</i>     |
| S/N TOTAL |                                  |     |          | \$640.00                          |

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR & FRONT ACCIDENT AREAS & ETC.

*800*  
\$1,200.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL, FRONT BUMPER & ETC.

*800*  
\$1,000.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOTLID INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

*50*  
\$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

*50*  
\$120.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

*60*  
\$120.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

*40*  
\$80.00

LABOUR TOTAL \$2,640.00

TING AN

TOTAL \$8,153.50

### Head office

8 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

