

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 03.03.2023

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMW5665Z**
MODEL : **BMW 216i**
DATE OF ACCIDENT : 03.03.2023
TIME OF ACCIDENT : 09:40 HOURS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Del d</i>	1	\$ 1,372.00	\$ 1,372.00
2	REAR BUMPER SENSOR <i>Del d.</i>	2	\$ 341.00	\$ 682.00
3	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 46.00	\$ 184.00
4	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 422.00	\$ 422.00
5	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 40.00	\$ 40.00
6	REAR BUMPER SIDE BRACKET (PLASTIC) <i>new</i>	2	\$ 177.00	\$ 354.00
7	REAR BUMPER CENTER BRACKET (UPPER) <i>used</i>	2	\$ 159.00	\$ 318.00
8	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 513.00	\$ 513.00
9	REAR FENDER INNER COWLING <i>2</i>	2	\$ 189.00	\$ 378.00
10	REAR FENDER INNER TRIM	2	\$ 487.00	\$ 974.00
11	TAIL LAMP LOWER BRACKET	2	\$ 86.40	\$ 172.80
12	TAILGATE	1	\$ 1,266.00	\$ 1,266.00
13	TAILGATE LOGO <i>new</i>	1	\$ 75.00	\$ 75.00
14	TAILGATE EMBLEM '216i' <i>new</i>	1	\$ 114.00	\$ 114.00
15	TAILGATE INNER LOCK	1	\$ 343.00	\$ 343.00
16	TAILGATE INNER LOCK MOTOR	1	\$ 595.00	\$ 595.00
17	TAILGATE LOCK CATCH	1	\$ 55.00	\$ 55.00
18	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 188.00	\$ 188.00
19	TAILGATE INNER BOARD <i>new</i>	1	\$ 298.00	\$ 298.00
20	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 210.00	\$ 210.00

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMW5665Z
 MODEL : BMW 216i
 DATE OF ACCIDENT : 03.03.2023
 TIME OF ACCIDENT : 09:40 HOURS

21	REAR END PANEL	1	\$ 747.00	\$ 747.00	X
22	REAR END PANEL TOP GARNISH	1	\$ 146.00	\$ 146.00	X
23	REAR FLOOR PANEL TOP BOARD	1	\$ 714.00	\$ 714.00	X

2562
 2433.90

TOTAL PRICE \$ 10,160.80
 LESS 5% \$ 508.04
 SUB TOTAL PRICE \$ 9,652.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00	X
2	REAR BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00	X
3	TAILGATE SEALANT	1	\$ 150.00	\$ 150.00	X
4	TAILGATE INNER BOARD CLIP (SET)	1	\$ 80.00	\$ 80.00	X
5	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	X
6	TAILGATE WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00	X
7	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 60.00	\$ 60.00	X
8	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 60.00	\$ 60.00	X
9	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	X

30

TOTAL \$ 770.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	250
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	250
3	TUFF COAT	\$ 250.00	X
4	WIRING AND BULB CHECK	\$ 250.00	X
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	X
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SMW5665Z
MODEL : BMW 216i
DATE OF ACCIDENT : 03.03.2023
TIME OF ACCIDENT : 09:40 HOURS

8	REMOVE AND REFIX VIDEO RECORDER	\$	100.00	x
9	TRANSFER TAILGATE MECHANISM	\$	80.00	x
10	CONDUCT WATER LEAKAGE TEST	\$	120.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$	180.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	680.00	x

TOTAL \$ 5,680.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,422.76
TOTAL LABOUR COST : \$ 5,680.00
TOTAL REPAIR COST : \$ 16,102.76

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
1/8 03/03/23.

03 Days

total: 30.3.90

1/8 2.4K

2.4K