


JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



PERFECT
AUTOWORK
PTE LTD

Ezlyra

DATE : 06.03.2023

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : CB7198X
MODEL : TOYOTA COASTER
DATE OF ACCIDENT : 21.02.2023
TIME OF ACCIDENT : 17:05 HOURS

JTGFP538003500536

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 3,439.00	\$ 3,439.00
2	REAR BUMPER SIDE BRACKET <i>But Dented</i>	2	\$ 185.00	\$ 370.00
3	REAR BUMPER BRACKET <i>But</i>	2	\$ 185.00	\$ 370.00
4	BACK PANEL RH <i>Dented</i>	1	\$ 4,855.30	\$ 4,855.30
5	BACK PANEL GLASS WEATHER STRIP RH <i>new</i>	1	\$ 228.60	\$ 228.60
6	BACK PANEL LOGO RH <i>new</i>	1	\$ 86.40	\$ 86.40
8	REAR DOOR INNER HANDLE LH <i>new</i>	1	\$ 159.30	\$ 159.30
9	REAR DOOR HINGE LH <i>new</i>	2	\$ 187.00	\$ 374.00
10	REAR DOOR LH <i>Dented</i>	1	\$ 3,452.90	\$ 3,452.90
11	REAR DOOR OUTER HANDLE LH <i>new</i>	1	\$ 198.70	\$ 198.70
12	REAR DOOR OUTER HANDLE GLASS WEATHERSTRIP <i>new</i>	1	\$ 105.30	\$ 105.30
13	REAR DOOR GLASS MOULDING LH <i>new</i>	1	\$ 228.00	\$ 228.00
14	REAR DOOR INNER TRIM LH <i>new</i>	1	\$ 295.00	\$ 295.00
15	REAR DOOR FRAME WEATHERSTRIP <i>new</i>	1	\$ 367.00	\$ 367.00
16	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 588.00	\$ 588.00
17	REAR DOOR WEATHERSTRIP PROTECTOR <i>new</i>	1	\$ 385.50	\$ 385.50
18	REAR DOOR HINGE LH <i>new</i>	2	\$ 187.00	\$ 374.00
19	REAR DOOR UPPER WEATHERSTRIP LH <i>new</i>	1	\$ 166.20	\$ 166.20
20	REAR END PANEL <i>Dented</i>	1	\$ 2,558.30	\$ 2,558.30
22	REAR FLOOR PANEL TOP MAT <i>new</i>	1	\$ 698.70	\$ 698.70

1950
2980
2950
1350

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : CB7198X
 MODEL : TOYOTA COASTER
 DATE OF ACCIDENT : 21.02.2023
 TIME OF ACCIDENT : 17:05 HOURS

23	RER CHASSIS CROSSMEMBER	1	\$ 1,952.30	\$ 1,952.30
----	-------------------------	---	-------------	-------------

10618.30
 7963.72

TOTAL PRICE \$ 21,252.50
 LESS 25% \$ 5,313.13
 SUB TOTAL PRICE \$ 15,939.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL LAMP CLIP (SET)	1	\$ 50.00	\$ 50.00
2	REAR DOOR GLASS SEALANT	2	\$ 80.00	\$ 160.00
3	REAR DOOR INNER BOARD CLIP (SET)	2	\$ 80.00	\$ 160.00
4	REAR DOOR STICKER 'EMERGENCY DOOR'	1	\$ 80.00	\$ 80.00
6	BACK PANEL SEALANT	1	\$ 180.00	\$ 180.00
7	BACK PANEL STICKER (AWC ROV)	1	\$ 40.00	\$ 40.00
5	REAR END PANEL SEALANT	1	\$ 150.00	\$ 150.00

300 TOTAL \$ 820.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	900
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
7	TRANSFER REAR DOOR MECHANISM	\$ 120.00	40
8	REMOVE & REINSTALL REAR DOOR GLASS	\$ 250.00	110

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : CB7198X
MODEL : TOYOTA COASTER
DATE OF ACCIDENT : 21.02.2023
TIME OF ACCIDENT : 17:05 HOURS

9	REMOVE & REINSTALL REAR WINDSCREE GLASS	\$ 250.00	X
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2130

TOTAL \$ 5,160.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,759.38
TOTAL LABOUR COST : \$ 5,160.00
TOTAL REPAIR COST : \$ 21,919.38

Adrian Lj
r/s 06/03/23
06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 10393.72

4/s: 8.3K

8.3K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: