

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 27 Mar 2023

**Preliminary Advice**

Vehicle No	: XE3469B	Accident Date	: 10/03/2023
Make	: UD TRUCKS GKB5ALDHCQA	Policy No.	: SP2002755946
Assignment Date	: 23/03/2023	Excess	: S\$2,500.00
Date of Inspection	: 24/3/2023	Est. Duration of Repair	: 10
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,310.00
Revised Amount	:S\$	15,279.50
Check Items (Estimated)	:S\$	14,049.50
Total	:S\$	29,329.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	16,534.00
Salvage Value	:S\$	
Margin for Repair	:S\$	88,466.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .