

CS/ A1823003063/Try3

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No.200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002755946	Date of Loss:	10/03/2023
Vehicle Reg. No.:	XE3469B	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CITY CONTAINER (S) PTE. LTD.	Contact No:	+6592990599
Driver:	MOHAMMAD FAZLEE BIN MOHAMAD EFFENDY		
Make/Model:	UD TRUCKS GKB5ALDHCQA, 7.5 D (M)	Vehicle Reg. Date:	25/09/2017
Vehicle Colour:	YELLOW		
Engine No:	GH11743075	Chassis No:	JNCM1F1AXHU020361
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	26,580.00
Miscellaneous Items	0.00
Labour	4,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	31,310.00
+ GST 8.00% (S\$)	2,504.80
Nett Amount (S\$)	33,814.80

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Mar 2023)
 Parts: N/A UD TRUCKS GKB5ALDHCQA 7.5 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/XE3469B/23/03/2023 15:29
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER (CTR)	0.00	0.00	bt ✓ *485.00 F
2	1		*FRT BUMPER (RH)	0.00	0.00	H ✓ *400.00 F
3	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	Xm ✓ *750.00 F
4	1		*FRT BUMPER LOWER GRILLE	0.00	0.00	ms ✓ *130.00 F
5	1		*FRT HEADLAMP (RH)	0.00	0.00	an ✓ *600.00 F
6	1		*FRT FOGLAMP (RH)	0.00	0.00	an ✓ *100.00 F
7	1		*FRT SIGNAL LAMP (RH)	0.00	0.00	an ✓ *50.00 F
8	1		*FRT BUMPER SIDE (RH)	0.00	0.00	bl ✓ *55.00 F
9	1		*FRT PANEL HINGE (RH)	0.00	0.00	unx ✓ *65.00 F
10	1		*FRT PANEL INNER REINFORCEMENT	0.00	0.00	unx ✓ *700.00 F
11	1		*FRT PANEL LOWER GRILLE (TOP)	0.00	0.00	an ✓ *220.00 F
12	1		*FRT PANEL LOWER GRILLE (BOTTOM)	0.00	0.00	an ✓ *240.00 F
13	1		*FRT PANEL LOCK	0.00	0.00	unx ✓ *60.00 F
14	1		*FRT PANEL LOCK CABLE	0.00	0.00	unx ✓ *110.00 F
15	1		*FRT PANEL LOCK LATCH	0.00	0.00	unx ✓ *25.00 F
16	1		*FRT CORNER PANEL (RH)	0.00	0.00	bl ✓ *335.00 F
17	1		*FRT WINDSCREEN	0.00	0.00	X un ✓ *950.00 F
18	1		*FRT WINDSCREEN RUBBER	0.00	0.00	an ✓ *310.00 F
19	1		*FRT WINDSCREEN ERP BRACKET	0	0.00	X un ✓ *26.00 FS
20	1		*FRT WINDSCREEN PILLAR	0.00	0.00	bl ✓ *1,400.00 F
21	1		*FRT WINDSCREEN PILLAR INNER (RH)	0.00	0.00	X un ✓ *900.00 F
22	1		*FRT WINDSCREEN PILLAR INNER TRIM (RH)	0.00	0.00	X un ✓ *140.00 F
23	1		*FRT STEP ALLOY (RH)(LOWER)	0.00	0.00	buw ✓ *180.00 F
24	1		*FRT STEP GARNISH (RH)(LOWER)	0.00	0.00	an ✓ *80.00 F
25	1		*FRT STEP ALLOY (RH)(TOP)	0.00	0.00	buw ✓ *180.00 F
26	1		*FRT STEP GARNISH (RH)(TOP)	0.00	0.00	an ✓ *350.00 F
27	1		*FRT STEP BRACKET @FRT	0.00	0.00	bl ✓ *320.00 F
28	1		*FRT STEP BRACKET @RR	0.00	0.00	bl ✓ *320.00 F
29	1		*FRT STEP GRANISH COVER (RH)	0.00	0.00	ms ✓ *45.00 F
30	1		*FRT WHEEL ARCH PANEL (RH)	0.00	0.00	bl ✓ *495.00 F
31	1		*FRT WHEEL ARCH GARNISH (RH)	0.00	0.00	dl ✓ *390.00 F
32	1		*FRT WHEEL ARCH PROTECTOR (RH)	0.00	0.00	dl ✓ *270.00 F
33	1		*FRT WHEEL ARCH STEP (RH)	0.00	0.00	X un ✓ *60.00 F
34	1		*FRT WHEEL SCUFF PLATE	0.00	0.00	X un ✓ *130.00 F
35	1		*FRT WHEEL ARCH INNERSHIELD (RH)	0.00	0.00	dl ✓ *170.00 F
36	1		*FRT WHEEL ARCH INNERSHIELD (TOP)	0.00	0.00	dl ✓ *180.00 F
37	1		*FRT DOOR RH	0.00	0.00	bl ✓ *2,100.00 F
38	1		*FRT DOOR HINGE (RH)	0.00	0.00	bl ✓ *65.00 F
39	1		*FRT DOOR TRIMBOARD (RH)	0.00	0.00	X un ✓ *350.00 F
40	1		*FRT DOOR RUBBER	0.00	0.00	an ✓ *195.00 F
41	1		*FRT DOOR GK420 STICKER	0.00	0.00	an ✓ *80.00 F
42	1		*FRT DOOR LOCK (RH)	0.00	0.00	X ✓ *275.00 F
43	1		*FRT DOOR LAMP (RH)	0.00	0.00	X ✓ *105.00 F
44	1		*FRT DOOR CHECKER (RH)	0.00	0.00	X ✓ *185.00 F
45	1		*FRT DOOR INNER MOULDING	0.00	0.00	X ✓ *185.00 F

Sng Ah Tee Motor & Panel Service Pte Ltd/XE3469B/23/03/2023 15:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRT DOOR GLASS REGULATOR	0.00	0.00	*245.00 F
47	1		*FRT DOOR GLASS MOTOR	0.00	0.00	*335.00 F
48	1		*FRT DOOR GLASS RUN CHANNEL	0.00	0.00	*210.00 F
49	1		*FRT DOOR GLASS INNER MOULDING	0.00	0.00	*185.00 F
50	1		*FRT DOOR PANEL (RH)	0.00	0.00	*900.00 F
51	1		*FRT DOOR PANEL INNERTRIM (RH)	0.00	0.00	*280.00 F
52	1		*STEERING BOX	0.00	0.00	*2,100.00 F
53	1		*FRT DASHBOARD	0.00	0.00	*2,300.00 F
54	1		*FRT SUPPORT BEAM	0.00	0.00	*1,200.00 F
55	1		*ACCELERATOR ASSY	0.00	0.00	*850.00 F
56	1		*BRAKE PEDAL ASSY	0.00	0.00	*750.00 F
57	1		*FRT PANEL LOCK (RH)	0.00	0.00	*50.00 F

F=Franchise part, S=SpocNett.

Sub Total (\$\$)	24,166.00
+ Margin on L,N Items 10.00% (\$\$)	2,414.00
Total Parts (\$\$)	26,580.00

Sng Ah Tee Motor & Panel Service Pte Ltd/XE3469B/23/03/2023 15:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK,WELD.REMOVE & REPLACE ABOVE PARTS	New	1500 2,000.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	1700 2,200.00
3	TO REMOVE & REFIX FRT DOOR GLASS (RH)	New	✓ 80.00
4	TO REMOVE & REFIX FRT DASHBOARD	New	200 X ^m 250.00
5	TO REMOVE & REPLACE FRT WINDSCREEN	New	✓ 150.00
6	TO CHECK WIRING	New	40 50.00
Gross Labour Cost (S\$)			4,730.00

Sng Ah Tee Motor & Panel Service Pte Ltd/XE3469B/23/03/2023 15:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495449
Wot Authorise E\$2500
Remark:
L/S Resurvey after repair.
taufik@hkauto.com
8-10 days
24/3/23 C 4:5pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: