

INSURER: **HL Assurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SNE4381G
Policy No:	MP321312	Date of Loss:	18/03/2023
Vehicle Reg. No.:	SNE4381G	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PEH TEOW PENG	Contact No:	+6591460348
Driver:	PEH TEOW PENG		

Make/Model:	HONDA FREED, 1.5 G (A)	Vehicle Reg. Date:	15/03/2022
Vehicle Colour:	BLUE		
Engine No:	L15B6562146	Chassis No:	GB53101858
Odometer:	5904 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair
(day) 10

*not Authorized
NKK means
31/3/23
\$4,455 + \$300
take photo before painting 5 days*

Present Location: ABWIN SERVICE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	5,385.50
Miscellaneous Items	0.00
Labour	2,800.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$)	8,185.50
- Excess (S\$)	300.00
(S\$)	7,885.50
+ GST 8.00% (S\$)	630.84
Nett Amount (S\$)	8,516.34

This claim is handled by: HAZELLYNN NATASYA CHNG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurers Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 23 Mar 2023)

Parts: M1-MPV

HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Abwin Service Pte Ltd/SNE4381G/23/03/2023 12:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH 3-65.27	0.00	0.00	580 *620.00 F
2	1		*FRONT DOOR HINGE UPPER RH 11	0.00	0.00	*40.00 F
3	1		*FRONT DOOR HINGE LOWER RH 11	0.00	0.00	*40.00 F
4	1		*FRONT DOOR HANDLE RH 11	0.00	0.00	*300.00 F
5	1		*FRONT DOOR REGULATOR RH 11	0.00	0.00	*370.00 F
6	1		*DOOR PILLAR RH 2	0.00	0.00	*610.00 F
7	1		*REAR SLIDING DOOR RH 3-65.27	0.00	0.00	580 *650.00 F
8	1		*REAR SLIDING DOOR HINGE UPPER RH 11	0.00	0.00	*85.00 F
9	1		*REAR SLIDING DOOR HINGE LOWER RH 11	0.00	0.00	*210.00 F
10	1		*REAR SLIDING DOOR HANDLE RH 11	0.00	0.00	*300.00 F
11	1		*REAR SLIDING DOOR REGULATOR RH 11	0.00	0.00	*380.00 F
12	1		*REAR SLIDING DOOR ROLLER RH 11	0.00	0.00	*250.00 F
13	1		*REAR FENDER RH 2	0.00	0.00	*690.00 F
14	1		*ROCKER PANEL RH 2	0.00	0.00	*200.00 F
15	1		*REAR DOOR GLASS MOUDLING RH 11	0.00	0.00	*60.00 F
16	1		*DOOR CLIPS 11	0	0.00	*50.00 FS
17	1		*ROCKER PANEL CLIPS 25	0	0.00	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,905.00
+ Margin on L,N Items 10.00% (S\$)	480.50
Total Parts (S\$)	5,385.50

Abwin Service Pte Ltd/SNE4381G/23/03/2023 12:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

P- 1130
102
P- 1243
1- 1530
2773

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New 600	1,000.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New 800	1,200.00
3	TO APPLY UNDERCOATING FOR RUST PROOFING	New ~1 X	180.00
4	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT RH DOOR COMPONENTS	New 50	150.00
5	TO DISMANTLE, REPLACE AND/OR REPAIR REAR RH DOOR COMPONENTS	New 60	150.00
6	TO CHECK WIRING	New 20	120.00
Gross Labour Cost (S\$)			2,800.00

Abwin Service Pte Ltd/SNE4381G/23/03/2023 12:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1530