

ASS. Ref: Taughin

REF:

05/F/123003067/Tuy 3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp: ed Vehicle No: _____

at Work: shop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: XE320R

Yr Regn: 2007 Dec

2008 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Truck with TM A.

Make: Nissan

CWB45

c.c. 13074

Colour: Yellow

A/C: Insured / Std / NI / NA

Sp. Reading: 616595

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: CWB4CLP00098

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/A / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: 21 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRI / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal. 8 mm

R/Bal. 8/8 mm

L/Bal. 8 mm

L/Bal. 8/8 mm

D.O.A. _____

D.O.I. 24/3/230/145

Survey held at Complete VMS

Des. of Damages Ft / Rear / O/S / N/S / U/C / Rooftop: or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. Sl. _____

Photos _____

Others _____

TOTAL

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.B. / (_____)



Chye Thiam Maintenance Pte Ltd
14, Tampines Industrial Drive,
Singapore 528530

Attention: Owner
Contact:

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES 010438
Date 24/3/2023
Vehicle Number XE320R
Make / Model NISSAN CWB45CLPHNB
Engine Number GE13334373B
Chassis Number CWB4CLP00098
Accident_Date 22 Mar 2023
Policy Number 5108281586-03-000059

Description	Qty	Unit Price	Amount
Parts			
List Items			
Rear Floor Board Frame	1	S\$8,000.00	S\$7,200.00 <i>bt ✓</i>
Side Board Hinge (RH)	2	S\$276.50	S\$497.70 <i>bt ✓</i>
Side Board R/H Latch	4 <i>5</i>	S\$312.20	S\$1,404.90 <i>bt ✓</i>
Side Board Frame R/H	1	S\$3,850.00	S\$3,465.00 <i>ora ✓</i>
Tail Gate	1	S\$2,450.00	S\$2,205.00 <i>ora ✓</i>
Tail Gate Hinge	4 <i>8</i>	S\$125.00	S\$900.00 <i>bt ✓</i>
Tail Gate Latch	2	S\$125.00	S\$225.00 <i>bt ✓</i>
Tail Lamp R/H	1	S\$612.30	S\$551.07 <i>mis ✓</i>
Tail Lamp Bracket	1	S\$296.20	S\$266.58 <i>mis ✓</i>
Rear Under Run Bar	1	S\$1,865.00	S\$1,678.50 <i>Rx</i>
Rear Under Run Bracket	2	S\$258.00	S\$464.40 <i>?</i>
Rear Mudflap R/H	2	S\$335.00	S\$603.00 <i>mis ✓</i>
Rear Mudflap Garnish	2	S\$112.00	S\$201.60 <i>mis ✓</i>
Rear Floor Board (wooden)	1	S\$3,850.00	S\$3,465.00 <i>?</i>
Rear Floor Board Cross Pillar	10		<i>?</i>
Side Railing R/H Guard	1	S\$1,120.00	S\$1,008.00 <i>bt ✓</i>
Discount 10% applied			\$24,135.75
Special Nett Items			
Company Logo (Side Board)	1	S\$500.00	S\$500.00 <i>250</i>
Arrow Board with Wire Controller	1	S\$45,000.00	S\$45,000.00 <i>bt ✓</i>

Pages

1 / 3

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



Chye Thiam Maintenance Pte Ltd
14, Tampines Industrial Drive,
Singapore 528530

Attention: Owner
Contact:

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg
The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE ES 010438
Date 24/3/2023
Vehicle Number XE320R
Make / Model NISSAN CWB45CLPHNB
Engine Number GE13334373B
Chassis Number CWB4CLP00098
Accident_Date 22 Mar 2023
Policy Number 5108281586-03-000059

Description	Qty	Unit Price	Amount
Arrow Board Frame	1	S\$8,000.00	S\$8,000.00 b7✓
TMA US100	1	S\$58,000.00	S\$58,000.00 bvc✓
TMA Bracket Mount	1	S\$8,000.00	S\$8,000.00 ?

?

Labour

To Send Chassis For Alignment Check

Nett

To Remove And Refit Damage Parts To Facilitate Repair (lorry body)	1		
Spray Paint Damage Affect Area	1		
Rust Proofing Treatment	1		
Check Wiring	1		1500
To Remove And Refit Damage Parts To Facilitate Repair (TMA)	1	S\$2,800.00	S\$2,800.00

Discount applied \$2,800.00

Pages

2 / 3

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin



Chye Thiam Maintenance Pte Ltd
14, Tampines Industrial Drive,
Singapore 528530

Attention: Owner
Contact:

Description

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

ESTIMATE	ES 010438
Date	24/3/2023
Vehicle Number	XE320R
Make / Model	NISSAN CWB45CLPHNB
Engine Number	GE13334373B
Chassis Number	CWB4CLP00098
Accident_Date	22 Mar 2023
Policy Number	5108281586-03-000059

Qty	Unit Price	Amount
Total		\$146,435.75

Taujiah 97495749
24/3/23 1145
L/S Resurvey after repair
taujiat@lkhauto.com
25 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pages

3 / 3

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin