

REPAIR ESTIMATE*

DATE: 21.02.21
MVA: RUMANN
DOA: 22.02.21

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	BOOTLID COVER <i>Dent/Buc</i>			\$2,179.18 ✓
	BOOTLID LOCK ?			\$275.00 ✓ P.O.
	BOOTLID EMBLEM - STAR <i>mcc</i>			\$45.46 ✓
	REAR SIDE BUMPER LH <i>XNW</i>			\$473.00 ✓ P.O.
	TAILAMP ASSY LH <i>cra</i>			\$622.44 ✓
	REAR BUMPER ASSY <i>B r</i>			\$1,372.00 ✓
	REAR BUMPER REINFORCEMENT <i>Dent</i>			\$462.48 ✓
10	REAR BUMPER CLIPS <i>mcc</i>			\$22.00 ✓
	BUMPER REINFORCEMENT BRACKET LH ?			\$141.14 XNW
	BUMPER REINFORCEMENT BRACKET RH ?			\$141.14 XNW
	REAR WINDSCREEN GLASS <i>B r</i>			\$1,273.98 ✓
	SUB TOTAL		6127.74	\$7,157.02
	LESS 20%		1225.54	\$1,431.40
	DISCOUNTED TOTAL		4902.19	\$5,725.62
1	REAR NUMBER PLATE			\$80.00 NET ✓
2	WINDSCREEN SEALANT			\$46.00 NET ✓
1	BOOTLID MAXI LOGO			\$80.00 NET ✓
1	REVERSE SENSOR			\$288.00 NET XNW
				\$494.00
	Labour Charge			\$1,200.00 900-
	PANEL BEATING			\$600.00 500-
	SPRAY PAINT			\$50.00 30-
	CHECK WIRING			\$50.00 30-
	TUFF KOTE			\$120.00 80-
	REMOVE/ REFIX REAR WINDSCREEN GLASS			\$80.00 50- 30-
	REMOVE/REFIX REVERSE SENSOR			
	4 days L/G 23/2/23 1st m 3pm <i>[Signature]</i>			
	TOTAL LABOUR			\$2,100.00
	ESTIMATE TOTAL		6578.19	\$8,319.62
			2nd = 1315.63	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

FT = 5250