

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|-----------------------|-----------------|-----------------------|------------|--|
| | STRIDES AUTOM | F | Ref: | CS/SMR23003075/Wvy3e2 | | |
| | 60 WOODLANDS I E4SINGAPORE 75 | С | Date: | 12/04/2023 | | |
| | | | C | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHB 5185L | Veh. Inspected | | SMU 3600J | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | TAX/03/23/2047 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 24/03/2023 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | MITSUBISHI LANCER 1.6 | c.c | | 1584 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2008 | |
| | Chassis No. | JMYSTCS3A7U012890 | Colour | | RED | |
| | Odometer | 270843 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 205/50 R16 | MICHELIN | | 7 mm | |
| | L/H Front Tyre | 205/50 R16 | MICHELIN | | 7 mm | |
| | R/H Rear Tyre | 205/50 R16 | MICHELIN | | 7 mm | |
| | L/H Rear Tyre | 205/50 R16 | MICHELIN | | 7 mm | |
| 4. | <u> </u> | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 20/03/2023 | Inspection Date | | 24/03/2023 | |
| | Survey held at JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047 | | | | | |
| | | | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |
| | 1 | | | | | |