



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003078/Uvy3e2	
			Date: 13/04/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 5491B	Veh. Inspected	SMF 6870E
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2301192/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	24/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 2 HATCHBACK (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JM6DJ2HAA01100492	Colour	GREY
	Odometer	102705 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R16	TOYO	7 mm
	L/H Front Tyre	185/60 R16	TOYO	7 mm
	R/H Rear Tyre	185/60 R16	TOYO	7 mm
	L/H Rear Tyre	185/60 R16	TOYO	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/03/2023	Inspection Date	24/03/2023
	Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	