

ASS. REC. BY:

REF: CS/CT 23003081/ACP3

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 32 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SND5893U Yr Regn: 2021, NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Noah Hybrid cc 1797Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR800505376Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/35R19R: 235/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 24/03/23Survey held at TSLDes. of Damages: 00 Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP Claim

6/7/2023 Adrian Finalised L8 \$52,000; 32 days with repairer. (Red 31,600.83,372)

MV: 180K.

PV: 86.7K.

Nett: 93.3K.

057H

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 32

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Inve (\$Report Format: TP

Insured Sum / L.P. P.C. \$52,000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	057H
Vehicle Details	
Vehicle No.:	SND5893U
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH 1.8X HYBRID CVT
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	2ZR2M77511
Chassis No.:	ZWR800505376
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,266.00
Original Registration Date:	29 Nov 2021
First Registration Date:	29 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$23,573.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2031
PARF Rebate Amount:	\$17,679.00
Intended COE Rebate Details	
COE Expiry Date:	28 Nov 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$79,601.00
COE Rebate Amount:	\$69,009.00
Total Rebate Amount:	\$86,688.00

The information contained herein is correct as at 27 Mar 2023

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing

Drive into the festive season with 3.28% p.a. by GV Cars Financing!

GV Automobile Centre StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Save Search](#)

Sort by [Date Posted](#) 20 results/page

7 vehicles Any Category [Advanced Search](#) [Search](#)

Search Selection	NOAH HYBRID	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
		Any	Any	< 2 year(s) old	Any	Any	Any	Any	Any	Available
	☐ Toyota Noah Hybrid 1.8A X Fuel Type: Petrol-Electric 1 owner. Excellent condition and well maintained, perfect MPV for the whole family and easy to maintain with comfortable legroom space and ample boot space, extremely neat and clean interior and exterior. No gimmicks! Trade in welcome! Call us for a non obligatory viewi... Se7en Motor Pte Ltd ☆ Posted: 23-Mar-2023	\$177,777	\$20,300 /yr	08-Jun-2021	1,797 cc	32,000 km	MPV	Available	PREMIUM AD	
	☐ Toyota Noah Hybrid 1.8A X Fuel Type: Petrol-Electric 1 owner mint condition! Rarely Drive Unit! Condition like brand new car. Full loan available. Fast loan approval with flexible financing! PHV welcome, low interest rates, buy with confidence! Please call for inquiry. Emperor Motors Pte Ltd ☆ Posted: 24-Mar-2023	\$180,800	\$20,480 /yr	30-Jun-2021	1,797 cc	16,088 km	MPV	Available	PREMIUM AD	
	☐ Toyota Noah Hybrid 1.8A X Fuel Type: Petrol-Electric Almost like new unit! Pristine condition! Very well maintained by previous owner! Full body kit! Regularly groom. Original manufacturer paintwork and upholstery. Flexible finance scheme with speedy process! High loan option available! Trade in option available! Immediate... Car (S) Pte Ltd ☆ Posted: 23-Mar-2023	\$186,800	\$20,920 /yr	06-Aug-2021	1,797 cc	-	MPV	Available	PREMIUM AD	
	☐ Toyota Noah Hybrid 1.8A Fuel Type: Petrol-Electric Immaculate Condition From Interior To Exterior. 120 Points STA Check And Accident Free Report Deal For A Peace Of Mind. High/Flexible Loan Available. Trade In Welcome. View By Appointment. 360 VR Cars ☆ Posted: 17-Mar-2023	\$192,000	\$19,650 /yr	28-Jul-2022	1,797 cc	-	MPV	Available		
	☐ Toyota Noah Hybrid 1.8A X Fuel Type: Petrol-Electric PHV Are Welcome. Reasonable Interest Rates, Please Call For more information! VINCAR Pte Ltd ☆ Posted: 13-Mar-2023	\$196,988	\$20,100 /yr	25-Aug-2022	1,797 cc	11 km	MPV	Available	PREMIUM AD	
	☐ Toyota Noah Hybrid 1.8A X Fuel Type: Petrol-Electric Newly Registered! PHV Are Welcome. Reasonable Interest Rates and various flexible loan plans. Please Call For more information! VINCAR Pte Ltd ☆ Posted: 15-Mar-2023	\$196,988	\$19,740 /yr	02-Nov-2022	1,797 cc	11 km	MPV	Available	PREMIUM AD	

TSL AUTO GARAGE

VEHICLE DETAILS

VEHICLE NO : SND5893U 2021 NOV
 VEHICLE MODEL : TOYOTA NOAH HYBRID
 CHASSIS NO : ZWR800505376

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Distal</i>	1	\$ 1,050.40	\$ 1,050.40
2	FRONT BUMPER SIDE HOLDER <i>Distal</i>	2	\$ 75.30	\$ 150.60
3	FRONT BUMPER LOWER GRILLE <i>Distal</i>	1	\$ 225.10	\$ 225.10
4	REAR BUMPER REINFORCEMENT <i>But</i>	1	\$ 371.30	\$ 371.30
5	FRONT BUMPER SPONGE <i>Distal</i>	1	\$ 156.90	\$ 156.90
6	FRONT BUMPER FOG LAMP <i>new</i>	2	\$ 305.40	\$ 610.80
7	FRONT BUMPER FOG LAMP COVER <i>Distal</i>	2	\$ 124.20	\$ 248.40
8	FRONT BUMPER UNDERCOVER <i>torn</i>	1	\$ 345.90	\$ 345.90
9	FRONT GRILLE <i>Distal</i>	1	\$ 1,194.40	\$ 1,194.40
10	FRONT GRILLE LOGO <i>new</i>	1	\$ 75.90	\$ 75.90
11	HEADLAMP <i>Distal</i>	2	\$ 3,384.20	\$ 6,768.40
12	FRONT BRACE PANEL <i>But</i>	1	\$ 122.10	\$ 122.10
13	FRONT SUPPORT PANEL <i>Distal</i>	1	\$ 945.10	\$ 945.10
14	FRONT SUPPORT PANEL TOP GARNISH <i>Distal</i>	1	\$ 290.10	\$ 290.10
15	FRONT FENDER <i>new</i>	2	\$ 911.20	\$ 1,822.40
16	FRONT FENDER INNER SHIELD <i>new</i>	2	\$ 232.90	\$ 465.80
17	FRONT FENDER BRACKET <i>new</i>	2	\$ 59.60	\$ 119.20
18	BONNET <i>Distal</i>	1	\$ 1,055.30	\$ 1,055.30
19	BONNET LOCK <i>new</i>	1	\$ 188.90	\$ 188.90
20	BONNET HINGE <i>But</i>	2	\$ 85.10	\$ 170.20
21	BONNET MOULDING <i>Distal</i>	1	\$ 326.40	\$ 326.40
22	BONNET INSULATOR <i>new</i>	1	\$ 219.60	\$ 219.60
23	BONNET WEATHERSTRIPE <i>new</i>	1	\$ 78.40	\$ 78.40
24	HORN <i>new</i>	2	\$ 92.30	\$ 184.60
25	FRONT DOOR <i>Distal</i>	2	\$ 1,672.30	\$ 3,344.60
26	FRONT DOOR LOCK <i>new</i>	2	\$ 397.10	\$ 794.20
27	FRONT DOOR WEATHERSTRIPE <i>new</i>	2	\$ 289.90	\$ 579.80
28	AIR CON CONDENSER <i>Distal</i>	1	\$ 1,233.10	\$ 1,233.10
29	AIR CON CONDENSER SIDE GUIDE UPPER <i>new</i>	2	\$ 24.50	\$ 49.00
30	AIR CON CONDENSER SIDE GUIDE LOWER <i>new</i>	2	\$ 26.80	\$ 53.60
31	AIR CON FAN BLADE <i>Distal</i>	1	\$ 164.90	\$ 164.90
32	AIR CON FAN MOTOR <i>new</i>	1	\$ 504.90	\$ 504.90
33	AIR CON SUCTION PIPE <i>new</i>	1	\$ 407.40	\$ 407.40
34	AIR CON DISCHARGE PIPE <i>new</i>	1	\$ 439.40	\$ 439.40
35	AIR CON LIQUID PIPE <i>new</i>	1	\$ 294.60	\$ 294.60
36	RADIATOR <i>Distal</i>	1	\$ 1,552.30	\$ 1,552.30
37	RADIATOR TOP PANEL <i>Distal</i>	1	\$ 441.50	\$ 441.50
38	RADIATOR TOP HOSE <i>new</i>	1	\$ 65.40	\$ 65.40
39	RADIATOR SPARE TANK <i>Distal</i>	1	\$ 129.70	\$ 129.70

1672.30

40	RADIATOR FAN COWLING	Crushed	1	\$	360.80	\$	360.80
41	RADIATOR FAN BLADE	New	1	\$	164.90	\$	164.90
42	RADIATOR FAN MOTOR	Good	1	\$	510.40	\$	510.40
43	OIL COOLER	Best	1	\$	684.10	\$	684.10
44	FRONT ENGINE MOUNTING	Good	1	\$	289.30	\$	289.30
45	FRONT ENGINE MOUNTING BRACKET	Good	1	\$	105.60	\$	105.60
46	AIR CLEANER	Crushed	1	\$	455.90	\$	455.90
47	INTAKE MANIFOLD	New Good	1	\$	449.20	\$	449.20
48	WIPER PANEL GARNISH	Wt	1	\$	488.20	\$	488.20
49	WIPER PANEL SIDE GARNISH	New	2	\$	48.10	\$	96.20
50	REAR BNUMBER PLATE LAMP	Crushed	2	\$	78.90	\$	157.80
51	REAR BUMPER	Distorted	1	\$	1,025.50	\$	1,025.50
52	REAR BUMPER SIDE HOLDER	Good	2	\$	70.90	\$	141.80
53	REAR BUMPER TOW COVER	Distorted	1	\$	28.10	\$	28.10
54	REAR END PANEL	Distorted	1	\$	735.70	\$	735.70
55	REAR END PANEL TOP GARNISH	Distorted	1	\$	148.60	\$	148.60
56	REAR END PANEL ANTENNA SENSOR	Missing	1	\$	184.60	\$	184.60
57	TAILLAMP	Smashed	2	\$	685.10	\$	1,370.20
58	TAILLAMP OUTER PANEL	Distorted	2	\$	311.10	\$	622.20
59	TAILLAMP OUTER PANEL LOWER	Distorted	2	\$	288.50	\$	577.00
60	TAILLAMP INNER PANEL	Distorted	2	\$	398.10	\$	796.20
61	TAILLAMP LOWER APRON	Distorted	2	\$	178.80	\$	357.60
62	TAILGATE	Distorted	1	\$	1,812.70	\$	1,812.70
63	TAILGATE LOCK	Tampered	1	\$	375.10	\$	375.10
64	TAILGATE LOWER LOCK CATCH	Best	1	\$	38.90	\$	38.90
65	TAILGATE WEATHERSTRIPE	Wt	1	\$	375.10	\$	375.10
66	TAILGATE OUTER MOULDING	Smashed	1	\$	581.50	\$	581.50
67	TAILGATE INNER TRIM BOARD	Distorted	1	\$	761.80	\$	761.80
68	TAILGATE INNER TRIM BOARD (SIDE)	Wt	2	\$	159.40	\$	318.80
69	TAILGATE INNER TRIM BOARD (UPPER)	New	1	\$	301.40	\$	301.40
70	TAILGATE DAMPER	Good	2	\$	326.80	\$	653.60
71	TAILGATE HINGE	Best	2	\$	113.40	\$	226.80
72	TAILGATE WIPER MOTOR	New	1	\$	773.90	\$	773.90
73	TAILGATE WIPER ARM	Good	1	\$	134.20	\$	134.20
74	TAILGATE WIPER ARM COVER	Good	1	\$	21.30	\$	21.30
75	TAILGATE GLASS	Shattered	1	\$	1,336.60	\$	1,336.60
76	TAILGATE GLASS MOULDING	New	1	\$	185.20	\$	185.20
77	TOYOTA LOGO	Good	1	\$	78.20	\$	78.20
78	HYBRID EMBLEM	Good	1	\$	58.40	\$	58.40
79	REAR FENDER	Distorted	2	\$	1,340.40	\$	2,680.80
80	REAR FENDER INNER TRIM BOARD	Crushed	2	\$	906.50	\$	1,813.00
81	REAR FENDER INNER TRIM BOARD UPPER	Distorted	2	\$	421.10	\$	842.20
82	REAR FENDER INNER SHIELD	Distorted	2	\$	125.90	\$	251.80
83	REAR FENDER RAIL GUIDE	New	2	\$	286.50	\$	573.00
84	REAR FENDER RAIL GUIDE COVER	Crushed	2	\$	316.10	\$	732.20
85	REAR FENDER GLASS	Shattered	2	\$	598.70	\$	1,197.40
86	REAR FENDER WHEEL HOUSE	Crushed	2	\$	848.40	\$	1,716.80
87	JACK COVER	Distorted	1	\$	128.70	\$	128.70
88	REAR SEAT BELT	Tampered	2	\$	760.10	\$	1,520.20
89	FLOOR PANEL	Distorted	1	\$	980.80	\$	980.80
90	FLOOR PANEL TOP BOARD	Distorted	1	\$	691.40	\$	691.40
91	FLOOR PANEL MAT	Torn	1	\$	582.40	\$	582.40
92	REAR AIR CON BLOWER	Crushed	1	\$	2,255.70	\$	2,255.70
93	ROOF PANEL	Crushed	1	\$	2,470.50	\$	2,470.50
94	ROOF PANEL INNER TRIM BOARD	Crushed	1	\$	1,684.30	\$	1,684.30

95	ROOF PANEL SIDE MOULDING <i>Dryd</i>	2	\$	212.40	\$	424.80	✓
96	REAR AXLE <i>Best</i>	1	\$	2,017.80	\$	2,017.80	✓
97	REAR WHEEL HUB C/W BEARING <i>dryd</i>	2	\$	524.20	\$	1,052.40	✓
98	BATTERY BRACKET <i>Best</i>	1	\$	248.40	\$	248.40	✓
99	SLIDING DOOR <i>RIA Buehard</i>	2	\$	1,594.80	\$	3,189.60	✓ 1594.80
100	SLIDING DOOR LOCK <i>Green</i>	2	\$	342.20	\$	684.40	✓
101	SLIDING DOOR WEATHERSTRIPE	2	\$	298.20	\$	596.40	✓
102	REAR EXHAUST PIPE <i>Best</i>	1	\$	892.50	\$	892.50	✓
103	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$	38.90	\$	38.90	✓
104	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$	35.20	\$	35.20	✓
105	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$	188.20	\$	188.20	✓

Rear Air Con Blower Air Duct. 249.80 ✓

TOTAL PRICE: \$ 74,686.40

LESS 25% \$ 18,671.60

SUB TOTAL PRICE: \$ 56,014.80

Front Air Duct. Dehd 104.90 ✓

62123.60

46592.70

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT NUMBER PLATE <i>Antid</i>	1	\$ 30.00	\$ 30.00	✓
2	FRONT NUMBER PLATE HOLDER <i>Dehd</i>	1	\$ 30.00	\$ 30.00	✓
3	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
4	FRONT BUMPER LOWER GARNISH <i>new</i>	1	\$ 400.00	\$ 400.00	✓
5	FRONT BUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
6	FRONT GRILLE CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
7	BONNET MOULDING CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
8	BONNET WEATHERSTRIPE CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
9	BONNET INSULATOR CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
11	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
12	AIR CON SIDE GARNISH CLIPS <i>new</i>	4 SET	\$ 10.00	\$ 40.00	✓
13	RADIATOR COOLANT <i>new</i>	1	\$ 40.00	\$ 40.00	✓
14	WIPER PANEL GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
15	FRONT DRIVER SEAT <i>new</i>	1	\$ 1,800.00	\$ 1,800.00	✓
16	REAR NUMBER PLATE <i>3rd hand</i>	1	\$ 30.00	\$ 30.00	✓
17	REAR NUMBER PLATE HOLDER	1	\$ 30.00	\$ 30.00	✓
18	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
19	REAR BUMPER REFLECTOR <i>Missing</i>	2	\$ 150.00	\$ 300.00	✓
20	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
21	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00	✓
22	TAILLAMP LOWER APRON CLIPS <i>new</i>	2 SET	\$ 20.00	\$ 40.00	✓
23	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
24	TAILGATE INNER TRIM BOARD (SIDE) CLIPS <i>new</i>	2 SET	\$ 20.00	\$ 40.00	✓
25	TAILGATE INNER TRIM BOARD (UPPER) CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
26	TAILGATE TOP SPOILER <i>sampled</i>	1	\$ 1,500.00	\$ 1,500.00	✓ 1200
27	TAILGATE TOP SPOILER BRAKE LAMP <i>Missing</i>	1	\$ 250.00	\$ 250.00	✓
28	TAILGATE GLASS SEALANT <i>3rd hand</i>	1	\$ 60.00	\$ 60.00	✓
29	TAILGATE GLASS SOLAR FILM	1	\$ 280.00	\$ 280.00	✓ 200
30	REAR CAMERA <i>Dryd</i>	1	\$ 450.00	\$ 450.00	✓ 400
31	REAR VIDEO CAMERA <i>Missing</i>	1	\$ 580.00	\$ 580.00	✓ SW
32	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
33	REAR FENDER INNER TRIM BOARD (UPPER) CLIPS <i>new</i>	2 SET	\$ 20.00	\$ 40.00	✓
34	REAR FENDER INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
35	REAR FENDER RAIL GUIDE COVER CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓
36	REAR FENDER SEALANT <i>new</i>	2	\$ 60.00	\$ 120.00	✓
37	REAR FENDER GLASS SEALANT <i>Nec</i>	2	\$ 40.00	\$ 80.00	✓

38	REAR FENDER GLASS SOLOR FILM <i>MR</i>	2	\$ 200.00	\$ 400.00	<i>300</i>
39	FLOOR PANEL TOP RUBBER TRAY <i>Delid</i>	1	\$ 350.00	\$ 350.00	<i>280</i>
40	FLOOR PANEL SEALANT <i>MR</i>	1	\$ 60.00	\$ 60.00	<i>✓</i>
41	REAR SEAT <i>Delid</i>	2	\$ 1,200.00	\$ 2,400.00	<i>✓</i>
42	ROOF PANEL INNER TRIM BOARD CLIPS <i>MR</i>	1 SET	\$ 100.00	\$ 100.00	<i>✓</i>
43	ROOF PANEL SIDE MOULDING CLIPS <i>MR</i>	2 SET	\$ 30.00	\$ 60.00	<i>✓</i>
44	REAR SHOCK ABSORBER <i>Delid</i>	2	\$ 500.00	\$ 1,000.00	<i>✓</i>
45	BATTERY <i>Delid</i>	1	\$ 200.00	\$ 200.00	<i>✓</i>
46	FRONT DOOR BLACK TAPE <i>RH MR</i>	2	\$ 60.00	\$ 120.00	<i>60</i>
47	FRONT DOOR VISOR <i>RH MR</i>	2	\$ 80.00	\$ 160.00	<i>80</i>
48	SLIDING DOOR BLACK TAPE <i>RH MR</i>	2	\$ 60.00	\$ 120.00	<i>60</i>
49	SLIDING DOOR VISOR <i>RH MR</i>	2	\$ 80.00	\$ 160.00	<i>80</i>

TOTAL : \$ 11,870.00

8610

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 6,800.00	<i>4900.</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 4,500.00	<i>3400.</i>	
3	W RING CHECK	\$ 200.00	<i>100</i>	
4	TO APPLY TUFF COAT	\$ 400.00	<i>250</i>	
5	TO REMOVE CONDENSER & TOP UP AIR CON GAS	\$ 120.00	<i>60</i>	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	<i>60</i>	
7	TO REMOVE INTAKE MANIFOLD	\$ 150.00	<i>✓</i>	
8	TO REMOVE FRONT DRIVER SEAT	\$ 150.00	<i>✓</i>	
9	TO REMOVE ENGINE MOUNTING	\$ 150.00	<i>✓</i>	
10	TO TRANSFER FRONT LH & RH DOOR FITTINGS	\$ 300.00	<i>80.</i>	
11	TO TRANSFER LH & RH SLIDING DOOR FITTINGS	\$ 300.00	<i>80.</i>	
12	TO DISMANTLE REAR UNDERCARRIAGE	\$ 450.00	<i>300.</i>	
13	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>80.</i>	
14	TO REMOVE REAR UPHOLSTERY & REAR LH & RH SEATS	\$ 380.00	<i>200</i>	
15	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
16	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	<i>50</i>	
17	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	<i>80</i>	
18	TO REPLACE TAILGATE GLASS	\$ 180.00	<i>120</i>	
19	TO VACCUM GLASS FRAGMENTS	\$ 100.00	<i>80</i>	
20	TO REMOVE ROOF INNER TRIM BOARD	\$ 200.00	<i>150</i>	
21	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>80.</i>	
22	TO REPLACE REAR LH & RH GLASSES	\$ 240.00	<i>120.</i>	
23	TOWING FEES	\$ 60.00	<i>✓</i>	

TOTAL: \$ 15,450.00

9800

ESTIMATE REPORT

TOTAL PARTS COST: \$ 67,884.80

TOTAL LABOUR COST: \$ 15,450.00

TOTAL REPAIR COST: \$ 83,334.80

83,600.83

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 65032700

L/S: 52K.

32 Days.

52K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: