



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: HO WINNIE		Ref: CS/HSB23003086/Kqp3e2 Date: 05/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 5397L	Veh. Inspected	SGV 1805P
Policy No.	VFX/P2413997	Coverage (\$)	0.00
Claim No.	S3M04KTQ	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	24/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053HY9305001649	Colour	METALLIC GREY
Odometer	186197 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	CONTINENTAL	9 mm
L/H Front Tyre	195/60 R15	CONTINENTAL	9 mm
R/H Rear Tyre	195/60 R15	BRIDGESTONE	7 mm
L/H Rear Tyre	195/60 R15	BRIDGESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/03/2023	Inspection Date	27/03/2023
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	